KCC OIL/GAS REGULATORY OFFICES

Date: <u>05/10/11</u>	District: <u>01</u>
	New Situation Lease Inspection
	Response to Request Complaint
	Follow-Up Field Report
Operator License No: 32204	
Op Name: Redland Resources, Inc.	Spot: NW-SE Sec 31 Twp 20 S Rng 25 $\mathbb{E} / \mathbb{V} $ W
Address 1: 6001 NW 23rd Street	· · · · · — —
Address 2:	
City: Oklahoma City	
State: <u>Ok.</u> Zip Code: <u>73127 – </u>	
Operator Phone #: <u>(405) 789-7104</u>	County: Ness
Reason for Investigation:	
Witness Alt.II	
Problem:	
None cement circulated to surface	
None dement directated to surface	•
Persons Contacted:	
Someone	
Findings:	
8-5/8" @ 221W/175sxs	•
TD @ 4500	
4-1/2" @ 4500'W/150sxs	
Port Collar @ 1656'W/350sxs cement-60	0/40-6%gel by Allied Cementing
·	
Action/Recommendations:	Follow Up Required Yes No 🗹 Date:
None, Alt.II requirements have been me	- 7
Trone, Ailli requirements have been me	RECEIVED
·	MAY 2 4 2011
RECEIVED (
MAY 9 0 2011	KCC WICHITA
WAY 20 ZUII	Photos Taken:
WAC DODGE CITY	
INDIVIS .	TA Program By: We War W
T-I Database District Files	Courthouse By. 1 2 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Other:	,
Rétain 1 Copy District Office Send 1 Copy to Conservation Division	

Date: <u>05/10/11</u>		_	District	: <u>01 </u>		Li	cense #: <u>32204</u>	
Op Name: 32204			Spot: <u>N</u>	Spot: <u>NW-SE</u>		Sec <u>31</u> Twp <u>2</u>	<u>0</u> S_Rng_ <u>25</u> E] w
County: Ness			Lease N	ame: <u>Ha</u>	rriet		Well #: <u>31-10</u>	
I.D. Sign Yes No				Gas Venting Yes No				
Tank Battery Cond	ition			Pi	ts .			
Condition: Good	Questional	ole Overflow	ving 🔊	Fluid	Depth:	ft; Approx. S	ize:ft. x	_ft.
Pits, Injection Site				S	ıltwater Pi	pelines	***	[5]
Fluid Depth:	_ft; Approx. S	Size:fi	t. xft.	Les	aks Visible	: Y N	Tested for Leaks: Y] N
Oil Spill Evidence				F	owing Hol	les		
Abandoned Well	Potential Poll	ution Problem [Yes No	Г	A Wells			
				Пм	lonitoring	Records		
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad				` · · · .	
SWD/ER Injection Well	Yes	No	Ness 🖻	Gaug	e Connect	ions Yes No		<u> </u>
Permit #: Pi	ressure – Actu	al: psi; Au	thorized: psi	Ťubi	ng:	; T/C Annulus:	; C/SP Annulus:	
Permit #: Pr	ressure – Actu	al: psi; Au	thorized: psi	Tubi	ng:	; T/C Annulus: _	; C/SP Annulus:	
Permit #: Pi	ressure – Actu	al: psi; Au	thorized: psi	Tubi	ng:	; T/C Annulus: _	; C/SP Annulus:	
Permit #:Pi	ressure – Actu	al: psi; Au	thorized: psi	Tubi	ng:	; T/C Annulus: _	; C/SP Annulus:	
API Number	Footages	Spot, Location	GPS		Well#		Well Status	
<u>15-135-25,226-00-00</u>	1987FSL 1904FEL	NW-SE	38.26740-100.	12429	31-10	New well, Alt,II co	ompleted	
				-				<u> </u>
				· · · · · · · · · · · · · · · · · · ·				
			•			,	ė	
* 1						. /		
			:		,			
		i .	T .		1	1		_

Retain 1: Copy District Office Send 1 Copy to Conservation Division

Form: