

DISTRICT CONSERVATION AGENT'S REPORT

*R*

TO:

State Corporation Commission  
Conservation Division  
800 Bitting Building  
Wichita, Kansas

FILE NO. 87-11  
LOCATION CSE-SE-SE <sup>NE</sup> *KCC*  
SEC 26 TWP. 15 RGE. 4N

Dry Hole  Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have today completed supervision of plugging of:

Well No. 1 Lease Nelson  
Operator Mr. H. Peter Co Address Salina Kans  
Field ✓ County Saline  
Total Depth 3418 Feet.

(Describe briefly the manner in which the well was plugged)

*Gravel pits & circulated  
Bridge at approx 185  
15 sack cement spotted thru  
6 joints of drill pipe.  
5 sack cement at top of surface  
pipe.*

*It is my opinion that  
the cementing of surface pipe was a  
poor job*

*[Signature]*  
District Conservation Agent

Date 3-30-53

**PLUGGING**

FILE SEC 26 TWP. 15 RGE. 4N  
BOOK PAGE 87 LINE 11

**RECEIVED**  
STATE CORPORATION COMMISSION

MAR 31 1953  
3-31-53  
CONSERVATION DIVISION  
Wichita, Kansas