
KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO: Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas

Remarks: U



| Wichita 2, Kansas | | | | • | | | | | |
|-------------------------------|--|--|--|--|---|---|---------------------------------------|---------------------------------------|---|
| File No. | County:_ | | Sal | ine | · · · · · · · · · · · · · · · · · · · | namentary name of the first | - Land Care Control | · . | |
| Location: NW-SW-SE | · | _Sec | 3 | Twp。 | 15 | _Rge | 1 | _(E)_ | (W) <u>X</u> |
| Name of Field: Wild | cat | | | Total | Depth | 0 * ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | 2570 | | |
| I have this date completed su | pervision of | plugg | ing o | E: | • | | | | |
| Lease Name: Peck | . Co | | | all and the second second second second | Wel | 1 No | 1 | , , | |
| Operator's Full Name: Don | , | | | | ······································ | · | · · · · · · · · · · · · · · · · · · · | | |
| Complete Address: 812 Hanc | ,, | | | | | | | · · · · · · · · · · · · · · · · · · · | |
| Plugging Contractor: Greenl | and Drilli | ng Co | } | | von Mayotto de la composition della composition | | | | |
| Address: 403 Schweiter Bl | dg., Wichi | ta, Ka | nsas | and the second s | Lic | ense N | o | | |
| Oil WellGas Well | | | | | | | | | |
| Other well as hereafter indic | • | | | | | | | ···· | |
| Was any delay in plugging ope | erations caus | sed by | Conse | rvation | Divis | ion Ag | ent? | Yes | No X |
| If yes how long? | | | | | | | | | |
| 11 yes non rong. | ng ngunigana naningan an di dana mahin adalah dan da n magan magan ing menangkan dan dan dan dan dan dan dan dan | | | | gglyggyddiod yrdyngynddio y ir diddionagangynd | , | | | |
| | | | | | | | | | |
| Operation Completed: Hour 3 | 2:30 AM r |)av | 8 | Мо | nth | Apri | 1 | Ϋ́є | ar 1959 |
| The above well was plugged a | <i>t</i> | | | diana dia mandiferina dia dia dia dia dia dia dia dia dia di | | | | , | |
| Heavy mud circulated. H | | with h | neavv | mud t | o 110 | [a† | ug an | ıd ‡ | sack |
| hulls pushed to 110' and | | | | | | | | | |
| heavy mudbridgedceme | | | | | | | | | |
| iloavy mada-prinagodoome | 711 CO WI GII |) Sa cir. | J. 00 | | | | | | |
| | | | | | , | | | | |
| | and the state of t | | | | | | | | , , , |
| | | | ···· | | · · · · · · · · · · · · · · · · · · · | | | | , <u>, , , , , , , , , , , , , , , , , , </u> |
| | | ###################################### | | | <u></u> | | | | |
| | | . , | ······································ | - | | | · · · · · · · · · · · · · · · · · · · | | |
| | • | • | | ~ | 0// | 11 | \sim | 0 | · |
| 1 | | Sig | ned:_ | (X/C | nserva | tion I | ivisio | n Age | ent |
| | 12 / | 7 | | | | \mathcal{U} | | | |
| Reviewed: / / / Field Super | Nock visor | | | | | IGG | NIC | 7 | |

PLUGGING FILE SEC 3 T/3 R/W

BOOK PAGE 29 LINE 2/