

KCC OIL/GAS REGULATORY OFFICES

Date: 09/01/11

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 9408

API Well Number: 15-135-25,289-00-00

Op Name: Trans Pacific Oil Corporation

Spot: SE-SE-NW-SW Sec 2 Twp 18 S Rng 24 E / W

Address 1: 100 S Main Ste 200

1492 (1497) Feet from N / S Line of Section

Address 2: _____

1017 (1032) Feet from E / W Line of Section

City: Wichita

GPS: Lat: 38.51243 Long: 99.95101 Date: 9/1/11

State: Kansas Zip Code: 67202 -3735

Lease Name: Melody Well #: 2

Operator Phone #: (316) 262-3596

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None cement circulated to surface

RECEIVED

Persons Contacted:

SEP 23 2011
KCC WICHITA

Findings:

8-5/8" @ 222'W/150sxs
TD. @ 4474'
4-1/2" @ 4465'W/170sxs
Port Collar @ 1625' cemented with 155sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

Action/Recommendations:

Follow Up Required Yes No

Date: 7/14/09

None Alt.II Requirements have been met

RECEIVED

SEP 20 2011

Verification Sources:

Photos Taken: _____

KCC DODGE CITY

<input type="checkbox"/> RBDMS	<input checked="" type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____		

By: Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 09/01/11

District: 01

License #: 9408

Op Name: 9408

Spot: SE-SE-NW-SW Sec 2 Twp 18 S Rng 24 E W

County: Ness

Lease Name: Melody Well #: 2

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Gauge Connections Yes No

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.289-00-00	1497FSL 1032FWL	SE-SE-NW-SW	38.51243-99.95101	2	New well. Alt. II completed

Retain 1 Copy District Office
Send 1 Copy to Conservation Division