

KCC OIL/GAS REGULATORY OFFICES

Date: 08/28/11

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 3842

API Well Number: 15-101-22,304-00-00

Op Name: Larson Engineering Inc., dba Larson Operating Company-

Spot: S/2-SW-SW-SW Sec 29 Twp 18 S Rng 30  E /  W

Address 1: 562 W State Rd. 4

67 (75) Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

330 (329) Feet from  E /  W Line of Section

City: Olmitz

GPS: Lat: 38.45350 Long: 100.66697 Date: 8/28/11

State: Kansas Zip Code: 67564 -8561

Lease Name: Whiting-Dutoit Well #: 1-29

Operator Phone #: (620) 653-7368

County: Lane

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

\_\_\_\_\_

Findings:

8-5/8"@260"W/175sxs  
 TD@4650'  
 5-1/2"@4647"W/125sxs  
 Port Collar@2184'cemented with 175sxs-smd-1/4#flo seal-2%cc-20sxs to pit

RECEIVED  
 SEP 23 2011  
 KCC WICHITA

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None Alt.II requirements have been met.

RECEIVED  
 SEP 20 2011

Verification Sources: **KCC DODGE CITY**

Photos Taken: \_\_\_\_\_

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

By: Michael Maier  
Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_

Date: 08/28/11

District: 01

License #: 3842

Op Name: 3842

Spot: S/2-SW-SW-SW Sec 29 Twp 18 S Rng 30  E  W

County: Lane

Lease Name: Whiting-Dutoit Well #: 1-29

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Lane

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-101-22.304-00-00	75FSL 329FWL	S/2-SW-SW-SW	38.45350-100.66697	1-29	New well, Alt. II completed