KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/08/11</u>	District: <u>0</u>		Case #:			
	New S	ituation	L	ease Inspe	ction	
	Respo	nse to Request	- <u> </u>	omplaint		
	Follow	y-Up	F	ield Repor	t	
Operator License No: <u>5144</u>	API Well N	umber: <u>15-135-</u>	25.275-00 -	00		
Op Name: Mull Drilling Company, Inc.			•		S Rng 22 E /√W	
Address 1: 1700 N Waterfront Pkwy		988)			N/ S Line of Section	
Address 2: Bldg. 1200				har.	E / W Line of Section	
City: Wichita		3 <u>8.62812</u> _L				
State: Kansas Zip Code: <u>67206 -6637</u>	Lease Name	: Backstrom		v	Vell #: <u>1-29</u>	
Operator Phone #: (316) 264-6365	County: N	ess		• • • • • • • • • • • • • • • • • • • •		
Reason for Investigation:						
Witness Alt.II						
Problem:						
None, cement circulated to surface						
					·	
Persons Contacted:						
					,	
Findings:		· · · · · · · · · · · · · · · · · · ·	- *		on the five and the American	
8-5/8" @ 246' W/175sxs cement					RECEIVED	
TD @ 4550'					SEP 2 3 2011	
5-1/2" @ 4540' W/150sxs cement	1/1# flo o	aal 20/ aa 10ay	vo wont to	nit		
Port Collar @ 1763' cement with 190sxs-smd	-1/4# 110 St	3al-270CC-1USX	s went to	pit	KCC WICHITA	
			•			
					:	
			· 			
Action/Recommendations: Follow	Up Required	✓YesNo)c	Date:		
Alt.II requirements have been met.				•		
DECEMED (
RECEIVED						
SEP 2 0 2011						
Verification Sources KCC DODGE CITY			· ·		Photos Taken:	
	ΓA Program	n 141-1	ol Maiss			
	Courthouse	By: <u>Micha</u>	iei ivialer			
Other:						

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: <u>09/08/11</u> Distr				t: <u>01</u> License #: <u>5144</u>							
Op Name: <u>5144</u>					oot: <u>SW-NE-SW-SE</u> Sec <u>29</u> Twp <u>16</u> S Rng <u>2</u>			□E ✓ W			
County: Ness			Lease Na	me: <u>Ba</u>	ckstrom		Well #: <u>1-29</u>				
I.D. Sign Yes	No		S	Gas	Venting [Yes No		5			
Tank Battery Condition Condition: Good Questionable Overflowing				Pi Fluid		ft; Approx. Size	:ft. x _	ft.			
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. xft.					Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N						
Oil Spill Evidence	Potential Poll	ution Problem [Yes No 201		lowing Ho	les					
Lease Cleanliness Very Good S SWD/ER Injection Well Permit #: Pi	Yes _	•	Ness 🖫	Gaug		Records ions Yes No; T/C Annulus:	; C/SP Annu	ılus:			
Permit #: Pi	ressure – Actu	al:psi; Au	thorized: psi	Tubii	ng:	; T/C Annulus:	; C/SP Annı	ılus:			
Permit #: Pr	ressure – Actu	al: psi; Au	thorized: psi	Tubii	ng:	; T/C Annulus:	; C/SP Annı	ılus:			
Permit #: Pi	ressure – Actu	al: psi; Au	thorized: psi	Tubii	ng:	; T/C Annulus:	; C/SP Annı	ılus:			
API Number	Footages	Spot Location	GPS		Well #		Well Status				
15-135-25,275-00-00	988FSL 1728FEL	SW-NE-SW-SE	38.62812-99.77	12-99.77785		New well, Alt.II completed					
a .											
								···			
			77.00		-		· · · · · · · · · · · · · · · · · · ·				
,											