KCC OIL/GAS REGULATORY OFFICES

| Date: <u>09/06/11</u> | District: 01 | Case #: |
|--|--|--------------------------------|
| | New Situation | Lease Inspection |
| | Response to Request | Complaint |
| | Follow-Up | Field Report |
| Operator License No: <u>30742</u> | API Well Number: <u>15-171-20,82</u> | 8-00-00 |
| Op Name: Palomino Petroleum, Inc. | Spot: <u>NE-SW-SE-NW</u> Sec <u>24</u> | Twp19S Rng32E / ✓ W |
| Address 1: 4924 SE 84th St. | 2270 (2249) | Feet from N/ S Line of Section |
| Address 2: | 1781 (1818) | Feet fromE/VW Line of Section |
| City: Newton | GPS: Lat: <u>38.38948</u> Long: <u>1</u> | 00.80779 Date: 9/6/11 |
| State: Kansas Zip Code: 67114 -8827 | Lease Name: <u>Vulgamore Cattle C</u> | 0. Well #: 1 |
| Operator Phone #: <u>(316) 799-1000</u> | County: Scott | |
| Reason for Investigation: | | |
| Witness Alt.II | | |
| Problem: | | |
| None | | |
| | • | |
| Persons Contacted: | | |
| | •. | • |
| | | |
| Findings: | | |
| 8-5/8"@218'W/160sxs cement TD@4950' | | RECEIVED |
| 15-1/2"@4939'W/155sxs cement | | |
| Port Collar@2256-cemented with 135sxs-sm | ıd-1/4#flo seal-2%cc15sxs to | pit. SEP 2 3 2011 |
| (a) - 1 · | | KCC WICHITA |
| • | • | KCC MICHINA |
| | | • |
| | | |
| Action/Recommendations: Follo | w Up Required Yes No | Date: |
| None, Atl.II requirements have been met. | | |
| | | |
| RECEIVED | | |
| SEP 2 0 2011 | | |
| KCC DODGE CITY Verification Sources: | | Photos Taken: |
| ✓ RBDMS KGS | TA Program | |
| T-I Database District Files | Courthouse By: | · |
| Other: | Michael Ma | iler |

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form:

| Date: <u>09/06/11</u> | | | District: | 01 | | Lic | ense #: <u>30742</u> | |
|-------------------------------|--------------------|------------------|------------------|--------------------|------------------------------------|-----------------------------|---|-------------|
| Op Name: <u>30742</u> | | | Spot: <u>N</u> E | <u> -SW-</u> | SE-NW | Sec <u>24</u> Twp <u>19</u> | 9 S Rng <u>32</u> | E W |
| County: Scott | · | | Lease Na | me: <u>Vu</u> | ne: Vulgamore Cattle Co. Well #: 1 | | | |
| I.D. Sign Yes | No | • | · · | Gas V | Venting [| Yes No | | |
| Tank Battery Cond | | ble Overflow | ving 🙉 | Pluid | | ft; Approx. Siz | ze:ft. x | ft. |
| Pits, Injection Site | • | · | | | altwater P | ipelines | | ිට න |
| Fluid Depth: | _ft; Approx. S | Size:f0 | . xft. | <u> </u> | | | Tested for Leaks: | Y N |
| Oil Spill Evidence | | | Flowing Holes | | | | | |
| Abandoned Well | Potential Poll | ution Problem | Yes No 🔊 | Т | A Wells | | | |
| | | | | Monitoring Records | | | | |
| Lease Cleanliness Very Good S | atisfactory | Poor Ver | y Bad | | | · | | |
| SWD/ER Injection Well | Yes | No | Scott 📴 | Gaug | e Connect | ions Yes No | | [3] |
| Permit #: Pr | | | | Tubii | ng: | ; T/C Annulus: | ; C/SP Annulus | : |
| Permit #:Pı | | | | | | ; T/C Annulus: | | |
| Permit #:Pi | | | | | | ; T/C Annulus: | | |
| Permit #:Pi | ressure – Actu | al: psi; Aut | horized: psi | Tubii | 1g: | ; T/C Annulus: | ; C/SP Annulus | : |
| API Number | Footages | Spot Location | GPS | <u></u> | Well # | | Well Status | |
| 15-171-20,828-00-00 | 2249FNL 1818FWL | NE-SW-SE-NW | 38.38948-100.8 | 0779 | 1 | New well, Alt,II co | mpleted | , |
| | | | | | | | *************************************** | |
| | | | | | | | | |
| | | | 1780-1 | | _ | | • | |
| | | | | | | | | |
| | | | | | | | ; | |
| | | | | | | | | |
| <u> </u> | | I | | | L | l | | |

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: