KCC OIL/GAS REGULATORY OFFICES

Date: <u>07/25/11</u>	District: <u>01</u>		Case #:	Case #:					
	New Situation		Lease Inspection						
	Response to Req	luest	Complaint						
	Follow-Up		Field Report						
Operator License No: 4058	API Well Number:	15-135-25 277-0	10 - 00						
Op Name: American Warrior	Spot: SE-NW-SE-			21 DE /\tall					
Address 1: P.O. Box 399				S Line of Section					
Address 2: P.O. Box 783188	1840 (1842)			<u> </u>					
City: Garden City	GPS: Lat: 38.4390			: <u>7/25/11</u>					
State: Kansas Zip Code: 67846 -0399	Lease Name: Elton			1-32					
Operator Phone #: (620) 587-3224	County: Ness								
Reason for Investigation:									
Witness Alt.II									
Problem:									
None, cement circulated to surface									
Persons Contacted:									
Findings:									
8-5/8" @ 223W/150sxs cement									
TD @ 4288'									
5-1/2" @ 4287'W/175sxs cement Port Collar @ 1392' cemented with 125sxs-smd-1/4# flo seal-2%cc-10sxs went to pit									
1 of condition with 12-one only 17-11 no ocal 27000 10000 work to pit									
1									
Action/Recommendations: Follow	Up Required Yes	No ⊡	Date:						
Alt.II requirements have been met									
				_					
			RE	CEIVED					
			AUG	0 3 2011					
Verification Sources:			KCC Photos	WICHITA Taken:					
	A Program								
	A Program Courthouse By:	Michael Maier							
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								
Retain 1 Copy District Office									
Send I Conv to Conservation Division o									

KCC DODGE CITY

Form: 02/22/2008



Date: <u>07/25/11</u>		_	District	: <u>01.</u>		Li	cense #: <u>4058</u>	<u>. </u>
Ор Name: <u>4058</u>	Name: 4058 Spot:				SE-SW_	Sec <u>32</u> Twp <u>1</u>	8 S Rng <u>21</u>	E ✓ W
County: Ness	nty: Ness Lease				Name: <u>Elton</u> Well #: <u>1-32</u>			
1.D. Sign Yes	No		17	Gas V	enting [Yes No		S
Tank Battery Cond	_	ole Overflow	ring s	Pi Fluid		ft; Approx. S	ize:ft. x	ft.
Pits, Injection Site	_ft; Approx. S	iize:ft	t. xft.	\vdash	ltwater Pi		Tested for Leaks:	→ → → N
Oil Spill Evidence		11.49		FI	owing Hol	les		-
Abandoned Well	Potential Poll	ution Problem	Yes No 🔊		A Wells			
Lease Cleanliness Very Good S	atisfactory	Poor Very	y Bad	М	onitoring	Records		
SWD/ER Injection Well		•	Ness 🖸			ions Yes No		•
Permit #:P						; T/C Annulus: _ ; T/C Annulus: _		
Permit #: P Permit #: P						; T/C Annulus: _ ; T/C Annulus: _		
Permit #: P						; T/C Annulus: _		
API Number	Footages	Spot Location	GPS		Well#		Well Status	
<u>15-135-25.277-00-00</u>	927FSL 1842FWL	SE-NW-SE-SW	38.43905-99.6	7189	1-32	New well, Alt.II_c	ompleted	
								
				<u> </u>			<u> </u>	