KCC OIL/GAS REGULATORY OFFICES

Date: <u>07/26/11</u>	<u>/11 District: 01 Case #:</u>		#:	
	New Situat	w Situation Lease Inspection		spection
	Response 1	to Request	Complair	nt
	Follow-Up	•	Field Rep	oort
Operator License No: 4058		er: <u>15-083-21</u>	-	
Op Name: American Warrior	Spot: <u>SE-SW</u>	<u>-SE-SE</u> Sec	26 Twp 22	_S Rng <u>23</u> E / \subset \W
Address 1: P.O. Box 399	_50(71))	Feet from	N/ S Line of Section
Address 2: P.O. Box 783188	713 (71 :	3)	Feet from	E/W Line of Section
City: Garden City	GPS: Lat: <u>38.1</u>	1 <u>0214</u> Long	g: <u>99.80983</u>	Date: <u>7/26/11</u>
State: Kansas Zip Code: 67846 -0399	Lease Name: <u>G</u>	ood Earth -Obr	ate	Well #: <u>1-26</u>
Operator Phone #: <u>(620) 587-3224</u>	County: Hodg	jeman		
Reason for Investigation:				
Witness Alt.II				
Problem:				•
None, cement circulated to surface				
Persons Contacted:				
	·		_ 	
Findings:				
8-5/8" @ 265W/170sxs cement			•	
TD @ 4 4513'				
5-1/2" @ 4504'W/125sxs cement				
Port Collar @ 1428' cemented with 150sxs-s	md-1/4# flo sea	al-2%cc-20sx	s went to pit	
			•	•
Action/Recommendations: Follow	w Up Required	Yes No [Date: _	
Alt.II requirements have been met				RECEIVED
				AUG 0 3 2011
				KCC WICHITA
Verification Sources:				Photos Taken:
RBDMS KGS T	TA Program			
	Courthouse	By: <u>Michael I</u>	<u>Maier</u>	
Other: RECEIVED \				
				· 1
Retain 1 Copy District Office Aug. – 2 2011				

KCC DODGE CITY

Form: 02/22/2008

Date: <u>07/26/11</u>		_	District	: <u>01</u>		License #: 4058	_
Op Name: <u>4058</u> Spot: <u>S</u>			E-SW-S	SE-SE	Sec <u>26</u> Twp <u>22</u> S Rng <u>23</u> E 🗸 V	V	
County: Hodgeman Lease N			ame: <u>Go</u>	od Earth	h -Obrate Well #: 1-26	_	
1.D. Sign Yes	No			Gas V	Venting [Yes No	<u> </u>
Tank Battery Condiction: Good	_	ole Overflow	ing 🔊	Pi Fluid		ft; Approx. Size:ft. xft.	
Pits, Injection Site	_ft; Approx. S	Size:ft	. xft.	——	altwater Pi aks Visible	Pipelines Pipelines	-
Oil Spill Evidence	N-	•		FI	lowing Hol	oles	
Abandoned Well	Potential Poll	ution Problem	Yes No 17	Т	`A Wells		
Lease Cleanliness Very Good S	atisfactory	Poor Very	y Bad	М	lonitoring	, Records	
SWD/ER Injection Well Permit #:Pi Permit #:Pi Permit #:Pi	Yes	No al:psi; Aut al:psi; Aut al:psi; Aut	Hodgeman psi thorized: psi thorized: psi thorized: psi	Tubii Tubii Tubii	ng: ng: ng:	; T/C Annulus: ; C/SP Annulus:	
API Number	Footages	Spot Location	GPS		Well #	Well • Status	
15-083-21.706-00-00	71FSL 713FEL	SE-SW-SE-SE	3 <u>8.10214-99.8</u> (0983	1-26	New well, Alt.II completed	_
				-			