

KCC OIL/GAS REGULATORY OFFICES

Date: 07/25/11

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 9067

API Well Number: 15-135-25,248-00-00

Op Name: DayMar Resources

Spot: NE-SE-SE-SW Sec 23 Twp 20 S Rng 24  E /  W

Address 1: 234 W 11th Ste A

600 (579) Feet from  N /  S Line of Section

Address 2: P.O. Box 70

2325 (2312) Feet from  E /  W Line of Section

City: Hays

GPS: Lat: 38.29228 Long: 99.94392 Date: 7/25/11

State: Kansas Zip Code: 67601 -3805

Lease Name: Evel 'G' Unit Well #: 1

Operator Phone #: (785) 625-0020

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

Findings:

8-5/8" @ 305'W/175sxs cement  
 TD @ 4423'  
 5-1/2" @ 4423'W/125sxs cement  
 Port Collar @ 1501' cemented with 250sxs-smd-1/4# flo seal-2%cc--15sxs went to pit

RECEIVED  
AUG 03 2011  
KCC WICHITA

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None Alt.II requirements have been met.

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

RECEIVED  
AUG - 2 2011

KCC DODGE CITY

Form: \_\_\_\_\_

Date: 07/25/11

District: 01

License #: 9067

Op Name: 9067

Spot: NE-SE-SE-SW Sec 23 Twp 20 S Rng 24  E  W

County: Ness

Lease Name: Evel 'G' Unit Well #: 1

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.248-00-00	579FSL 2312FWL	NE-SE-SE-SW	38.29228-99.94392	1	New well. Alt. II completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_