## KCC OIL/GAS REGULATORY OFFICES

Date: <u>07/20/11</u>	District: <u>01</u>	<u></u>	Case	#:
	New Si	tuation	Lease Ins	pection
	Respon	se to Request	Complair	ıt
	Follow	-Սր	Field Rep	ort
Operator License No: 5259		mber: <u>15-083-21</u>	•	
Op Name: Mai Oil Operations, Inc.				_S Rng <u>24</u> E / \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Address 1: 8411 Preston Rd Ste 800		(2042)		N / S Line of Section
Address 2:		` '		E / W Line of Section
City: Dallas				Date: <u>7/20/11</u>
State: <u>Texas</u> Zip Code: <u>75225 -5520</u>	Lease Name:	Dechant		Well #: 1
Operator Phone #: (214) 219-8883	County: Ne	ess		
Reason for Investigation:				
Witness Atl.II				
Problem:				
None, cement circulated to surface.				
Persons Contacted:				
rersons contacted.		-		
Findings:				
8-5/8"@235/150sxs TD@4748' 5-1/2"@4744'/175sxs Port Collar@1758'/275sxs-60/40-6%gel-1/4#	flo seal20	sxs to pit.		
•				RECEIVED
				AUG 0 3 2011
Action/Recommendations: Follow	w Up Required	Yes No	🖸 Date: _	VCC MICHITA
None, Alt.II requirements have been met.				KCC WICHIA
Verification Sources:				Photos Taken:
<b>✓</b> RBDMS KGS	TA Program			
	Courthouse	Ву:		
Other:		_Michael	Maier	
Retain 1 Copy District Office RECEIVED Send 1 Copy to Conservation Division	· · · · · · · · · · · · · · · · · · ·			
JUL <b>2 9</b> 2011				Form:

KCC DODGE CITY

Date: <u>07/20/11</u>		_	District:	01	_	Lice	ense #: <u>5259</u>	
Op Name: <u>5259</u>				N-NE-N	E-SW	Sec <u>3</u> Twp <u>22</u>	S Rng <u>24</u>	E ✓ W
County: Ness			Lease Na	Name: Dechant Well #: 1				
I.D. Sign Yes	No		5	Gas Ve	enting [	Yes No		3
Tank Battery Cond		ole Overflow	ing	Pits		ft; Approx. Siz	e:ft. x	ft.
Pits, Injection Site Fluid Depth:	_ft; Approx. S	Size:ft	. xft.		twater Pi		ested for Leaks:	. Y N
Oil Spill Evidence				Flo	wing Hol	es		
Abandoned Well	Potential Poll	ution Problem [	Yes No 17	TA	A Wells			
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad	Mo	nitoring	Records		
SWD/ER Injection Well           Permit #:         P           Permit #:         P           Permit #:         P	Yes ressure – Acturessure – Actures – Actu	No al: psi; Aut al: psi; Aut al: psi; Aut		Tubing Tubing Tubing	g; g;	ions Yes No ; T/C Annulus: ; T/C Annulus: ; T/C Annulus: ; T/C Annulus:	; C/SP An	nulus: nulus:
API Number	Footages	Spot Location	GPS		Well #		Well Status	
15-083-21,710-00-00	2042FSL 2163FWL	SW-NE-NE-SW	38.16619-99.94	1702	1	New well, Alt,II cor	mpleted	
	ļ .							