

KCC OIL/GAS REGULATORY OFFICES

Date: 08/08/11

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 30742  
 Op Name: Palomino Petroleum, Inc.  
 Address 1: 4924 SE 84th St.  
 Address 2: \_\_\_\_\_  
 City: Newton  
 State: Kansas Zip Code: 67114 -8827  
 Operator Phone #: (316) 799-1000

API Well Number: 15-135-25,283-00-00  
 Spot: SE-NE-NW-SE Sec 33 Twp 16 S Rng 26  E  W  
2002 (1997) Feet from  N  S Line of Section  
1610 (1633) Feet from  E  W Line of Section  
 GPS: Lat: 38.61575 Long: 100.19904 Date: 8/8/11  
 Lease Name: Kandt Family Trust Well #: 1  
 County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None cement circulated to surface

Persons Contacted:

\_\_\_\_\_

Findings:

8-5/8" @ 219'W/150sxs cement  
 TD @ 4780'  
 5-1/2" @ 4772'-cemented with 175sxs cement  
 Port Collar @ 2004' cemented with 135sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None Alt.II requirements have been met.

RECEIVED  
AUG 17 2011

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

By: Michael Maier

PHOTOS TAKEN: KCC WICHITA

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

RECEIVED  
AUG 15 2011

KCC DODGE CITY

Form: \_\_\_\_\_

Date: 08/08/11

District: 01

License #: 30742

Op Name: 30742

Spot: SE-NE-NW-SE Sec 33 Twp 16 S Rng 26  E  W

County: Ness

Lease Name: Kandt Family Trust Well #: 1

I.D. Sign  Yes  No

---

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

---

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Oil Spill Evidence

---

Abandoned Well Potential Pollution Problem  Yes  No

---

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

---

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

---

Flowing Holes

---

TA Wells

---

Monitoring Records

SWD/ER Injection Well  Yes  No

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well Number	Well Status
15-135-25,283-00-00	1997FSL-1633FEL	SE-NE-NW-SE	38.61575-100.19904	1	New well, Alt, ll completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_