

KCC OIL/GAS REGULATORY OFFICE

15-071-20773-00-00

Date 10-14-03 + 10-16-03

- New Situation
- Response to Request
- Follow-up

ALTZ

Operator R.C. Banks #

Address

Location E12-NE-NW, Sec 29, T17 S, R40 W

Lease Roe Well # 3

Phone No.

County Greeley

Oper. Other

Reason for Investigation: ALT II completion cmt didn't circulate  
running bond log, (10-16-03) Perforated + Allied cementing pumped  
cmt

Problem:

RECEIVED

NOV 03 2003

Person(s) Contacted:

KCC WICHITA

Findings: Log-Tech of Kansas on location @ 9:00 am bond  
log. TOC @ 1608 recommend perforating @ 1520'  
1550 - 1600' maybe some cmt

(10-16-03) Log-Tech of Kans. perforated @ 1520' Allied pumped down 4 1/2  
1 bbl @ 800# squeezed w/ 25sx cam, waited 2 1/2 hrs. Perforated  
@ 1300' Tight 1 bpm @ 900#, pumped down 8 5/8 x 4 1/2 annulus. 5 bbl loaded pressured up  
to 600#. Squeezed perf w/ 50sx lite cmt + 25sx comm. photos taken:

Action/Recommendations: Drill squeeze out + run bond log agers.

alt II comp. 10-30-03 SID,

- Lease Inspection
- Complaint
- Field Report

By Kevin D Strube  
Kevin D Strube

## LEASE INSPECTION

YES

NONE COMMENTS

I.D. Sign

Tank Battery

; Condition: good  questionable  overflowing

Pits, tank battery

; Fluid depth \_\_\_\_\_ ft.; approx. size \_\_\_\_\_ ft x \_\_\_\_\_ ft

Pit, injection site

; Fluid depth \_\_\_\_\_ ft.; approx. size \_\_\_\_\_ ft x \_\_\_\_\_ ft

Gas venting

Oil spill evidence

Saltwater evidence

; Surface flow \_\_\_\_\_; seepage \_\_\_\_\_

Saltwater pipelines

; Seepage visible Yes/No; tested for leaks Yes/No

Flowing holes

Abandoned wells

TA wells

; Potential poll. Prob. \_\_\_\_\_; currently producing \_\_\_\_\_

SWD/ER Injection well

; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi

SWD/ER Injection well

; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi

SWD/ER Injection well

; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi

SWD/ER Injection well

; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi

Monitoring records

Gauge connections

; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_

Gauge connections

; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_

Gauge connections

; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_

Gauge connections

; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_

Lease cleanliness: Very good \_\_\_\_\_ satisfactory \_\_\_\_\_ poor \_\_\_\_\_ very bad \_\_\_\_\_

Water samples taken \_\_\_\_\_

Reports prepared \_\_\_\_\_

+	+	+	+
+	+	+	+
+	+	+	+
+	+	+	+