

R

KANSAS
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:
Jewel M. Ogden, Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

15-169-00055-0000

File No. _____ County: Saline

Location: NW-NW-SW Sec. 4 Twp. 16 Rge. 1 (E) (W) X

Name of Field: Mortimer Total Depth: 2700

I have this date completed supervision of plugging of:

Lease Name: Karber Well No. 1

Operator's Full Name: Francis M. Raymond

Complete Address: 410 4th National Bank Building, Wichita, Kansas

Plugging Contractor: Raymond Oil Co., Inc.

Address: 410 4th Natl. Bank Bldg., Wichita, Kansas License No. _____

Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ D & A X

Other well as hereafter indicated: _____

Was any delay in plugging operations caused by Conservation Division Agent? Yes _____ No X

If yes how long? _____ Reason: _____

Operation Completed: Hour 8:00 AM Day 8 Month November Year 1958

The above well was plugged as follows:

Heavy mud circulated. Hole filled to 190' with heavy mud--plug and $\frac{1}{4}$ sack hulls pushed to 190'--cemented with 20 sacks thru drill pipe.

Hole filled to 40' with heavy mud--plug and $\frac{1}{4}$ sack hulls pushed to 40'--cemented with 10 sacks. Rathole capped with 2 sacks.

Signed: Herbert J. Tomman
Conservation Division Agent

Reviewed: J. Lewis Brock
Field Supervisor

Remarks:

PLUGGING
FILE SEC. 4 T. 16 R. 1 W
BOOK PAGE 1 LINE 17

RECEIVED
STATE CORPORATION COMMISSION

DEC 2 - 1958

CONSERVATION DIVISION
Wichita, Kansas