KCC OIL/GAS REGULATORY OFFICES

Date: <u>11/04/11</u>	District: <u>01</u>	_	Case	#:	· · · · · · · · · · · · · · · · · · ·	
	New Situation	n	L .	Lease Inspection		
	Response to	Request	Complai			
	Follow-Up		Field Rep	oort		
Operator License No: 4058	API Well Number	: _15-069-203	352-00-00	*******		
Op Name: American Warrior, Inc.	Spot: <u>SW/NE/S</u>	SW/NW Sec	4 Twp 24	_S Rng <u>29</u>	□E /▼W	
Address 1: 3118 Cummings Rd.	1700		Feet from	ı √N/ SL	ine of Section	
Address 2: P.O. Box 399	750			لننا لننا		
City: Garden City	GPS: Lat:					
State: Kansas Zip Code: 67846 -	Lease Name: <u>O'E</u>					
Operator Phone #: <u>(620) 275-2963</u>	County: Gray		<u></u>			
Reason for Investigation:						
Company request KCC view Alt 2					·	
Problem:						
Alt 2 requirement not yet met						
Persons Contacted:				•		
Joe Smith						
Findings:	•		,			
Port Collar was set at 2969.5 Cemented by Swift with SMD 250 sx total, 30 in the pit					,	
Surface casing is 8 5/8 set at 523 with 30sx						
Production casing is 5 1/2 set at 4866 with 12	25 sx					
			<u>.</u>			
Action/Recommendations: Follow	w Up Required \[\]	es √No [Date: _	11/4/11		
				RECEI	/FD	
				•		
			,	NOV 1 8	2011	
			·	KCC WIC	HITA	
Verification Sources:				Photos Take	n: <u>No</u>	
	TA Program Courthouse	By: <u>Daniel B</u>	ernasconi		X1	
Retain 1 Copy District Office Send 1 Copy to Conservation Division V - 7 2011				Form: <u>11/</u> (04/2011	
KCC DODGE CITY				10m. <u>11/1</u>	77/ 4 V L I	

Date:				<u>U1</u>	_	License #: 4058		
-				SW/NE/SW/NW Sec 4 Twp 24 S Rng 29 \blacksquare E \checkmark W lame: O'Brate Well #: 4-6				
County: Gray			Lease Na	me: <u>O'Brate</u>	·	Well #: <u>4-6</u>		
I.D. Sign Yes	No		S	Gas Venting [Yes No		1 49	
Tank Battery Cond		Dle Overflow	ving	Pits Fluid Depth:	ft; Appro	ox. Size:ft.	xft.	
Pits, Injection Site			<u> </u>	Saltwater 1	Pinalinas			
Fluid Depth:		Size:f	t. xft.	Leaks Visib		Tested for Leaks	: Y N	
Oil Spill Evidence				Flowing H	oles			
Abandoned Well	Potential Poll	ution Problem [Yes No 5	TA Wells Monitoring	g Dagords			
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad	IVIOIIIO	g Records			
SWD/ER Injection Well Permit #: P Permit #: P	ressure – Actu	al: psi; Au al: psi; Au	thorized: psi	Tubing:		No . s:; C/SP An s:; C/SP An		
Permit #: P						s:; C/SP An		
Permit #:P		al: psi; Au	thorized: psi	Tubing:	; T/C Annulu	s:; C/SP An	nulus:	
API Number	Footages	Spot Location	GPS	Well#		Well Status		
:								
•						· · · · · · · · · · · · · · · · · · ·		