

KCC OIL/GAS REGULATORY OFFICES

Date: 11/17/11

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 33770

API Well Number: 15-135-25,311-00-00

Op Name: Ares Energy, LTD

Spot: NW-NW-NE-NW Sec 9 Twp 18 S Rng 21 E / W

Address 1: 405 N Marienfeld, Ste 250

5170 (5180) Feet from N / S Line of Section

Address 2: _____

1570 (1539) Feet from E / W Line of Section

City: Midland

GPS: Lat: 38.50883 Long: 99.65488 Date: 11/17/11

State: Texas Zip Code: 79701 -

Lease Name: Mantz Well #: 9-3

Operator Phone #: (432) 685-1960

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

Findings:

8-5/8" @ 310'W/200
TD @4458
5-1 1/2" @ 4685'W/125sxs
Port Collar @ 1444'W/150sxs-smd-1/4# flo seal-2%cc--10sxs to pit.

RECEIVED
DEC 01 2011
KCC WICHITA

Action/Recommendations:

Follow Up Required Yes No

Date: _____

None, Alt.II requirements have been met.

Verification Sources:

- RBDMS
- T-I Database
- Other: _____
- KGS
- District File
- TA Program
- Courthouse

KCC DODDGE CITY

RECEIVED

NOV 30 2011

Photos Taken: _____

By: Michael J. Martin

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: _____

Date: 11/17/11

District: 01

License #: 33770

Op Name: 33770

Spot: NW-NW-NE-NW Sec 9 Twp 18 S Rng 21 E W

County: Ness

Lease Name: Mantz Well #: 9-3

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.311-00-00	5180FSL 1539FWL	NW-NW-NE-NW	38.50883-99.65488	9-3	New well, Alt. II completed