Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Berexco LLC	License Number: 34318
Operator Address: 2020 N. Bramblewood, Wichita, KS 67206-1094	
Contact Person: Evan Mayhew	Phone Number: (316) 265 - 3311
Permit Number (API No. if applicable): 15-093-21853-00-00	Lease Name & Well No.: Patterson Unit #2-23
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NE SE
Settling Pit Drilling Pit	Sec. 23 Twp. 22S R. 38 ☐ East
Workover Pit ✓ Haul-Off Pit	Eest from North / ✓ South Line of Section
	Feet from
	Kearney County
Date of closure: 11 June 2010 Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the Bentonite clay in drilling mud, native mud & clays. Abandonment procedure of pit: Allowed liquid to evaporate until bottom of pit was dry, the close as possible to it's natural state.	
The undersigned hereby certifies that he / she is Engineering Techni a duly authorized agent, that all information shown hereon is true and correct to the	
Subscribed and sworn to me on this 12 day of DIANA E. BELL Notary Public - State of Kansas My Appt. Expires 9-10-11 My Commission Expires: 4-10 20	April 2011 Notary Public RECEIVED APR 1 4 2011

The Hub of Syracuse, Inc.

P.O. BOX 638-EAST HIGHWAY 50 SYRACUSE, KANSAS 67878 (620) 384-6914 FAX:(620) 384-7896

Invoice

p e

DATE:

6/11/2010

COMPANY NAME:

BEREXCO, INC.

808 S. FRONTAGE ROAD GARDEN CITY, KS 67846

LEASE NAME:

PATTERSON #2-23

(KE. CO.)

WORKING PIT, DRESS OFF & RIP. THEN BACKFILLED OFF SITE RESERVE PIT,

DESCRIPTION OF WORK/MATERIAL	HRS/QTY	RATE	AMOUNT
PUSHED LINER IN ON WORKING PIT AT			
WELL HEAD WHILE VACUUM TRUCK			
PULLED WATER OUT OF PIT, THEN			
STARTED BACKFILLING WORKING PIT.			I
PAYLOADER CARRIED REMAINING MUD			
TO OFF SITE RESERVE PIT, BACKFILL			

D-6H DOZER W/OP CAT 950 G LOADER W/OP

DRESSED OFF & BACKRIPPED.

RECEIVED APR 1 4 2011 KCC WICHITA