steve Pfeiter 12/21/01

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-1 April 2004 Form must be Typed

APPLICATION FOR SURFACE PIT

Submit in Duplicate

Operator Name: Timberline Oil & Gas Corporation			License Number: 9232
Operator Address: 4000 Penrose Place, Rapid City, SD 57702			
Contact Person: Brant C. Grote			Phone Number: (605) 341 - 3400
Lease Name & Well No.: Miskimen 1			Pit Location (QQQQ):
Type of Pit:	Pit is:		<u>NE . NW . SE</u>
Emergency Pit Burn Pit	Proposed Existing		Sec. 32 Twp. 26S R. 12W East West
Settling Pit Drilling Pit	If Existing, date constructed:		2310 Feet from North / South Line of Section
Workover Pit Haui-Off Pit (If WP Supply API No. or Year Drilled) 15-151-20598	Pit capacity:		Feet from East / West Line of Section County
Is the pit located in a Sensitive Ground Water Area? Yes No		Chloride concentration: mg/l	
Is the bottom below ground level? Yes No	Artificial Liner? ☐ Yes ☑ No		(For Emergency Pits and Sattling Pits only) How is the pit lined if a plastic liner is not used?
Pit dimensions (all but working pits): 20	Length (feet) 8		Width (feet) N/A: Steel Pits
Depth from ground level to deepest point:5(feet)			
Distance to nearest water well within one-mile of pit		Source of infor	
1900 feet Depth of water well 90 110 feet		measuredwell owner electric logKDWR	
Emergency, Settling and Burn Pits ONLY: Producing Formation:		Drilling, Workover and Haul-Off Pits ONLY: Type of material utilized in drilling/workover:	
Number of producing wells on lease:		Number of working pits to be utilized:	
Barrels of fluid produced daily:		Abandonment procedure: Backfill with bulldozer	
Does the slope from the tank battery allow all spilled fluids to flow into the pit? Yes No		Drill pits must be closed within 365 days of spud date.	
I hereby certify that the above statements are true and correct to the best of my knowledge and belief.			
December 27, 2006 Date		3	ignature of Applicant or Agent
KCC OFFICE USE ONLY			
Date Received: 18 7 Permit Number: 15-151-20598 Permit Date: 14/57 Lease Inspection: 7 Yes 12 No			