




KANSAS CORPORATION COMMISSION
CONSERVATION DIVISION
130 S. MARKET - ROOM 2078
WICHITA, KS 67202

CLOSURE OF SURFACE POND

OPERATOR NAME American Energies Corporation		LICENSE NO. 5399	
OPERATOR ADDRESS 155 North Market, Suite 710, Wichita, KS 67202			
CONTACT PERSON Alan L. DeGood, President		PHONE NUMBER (316) 263-5785	
PERMIT NUMBER (API NO. IF APPLICABLE) 15-115-20605-0000		LEASE NAME Scully H #1	
TYPE OF POND: <input type="checkbox"/> EMERGENCY PIT <input type="checkbox"/> TREATMENT PIT <input checked="" type="checkbox"/> WORKOVER PIT		PIT LOCATION: SE NW NE NE SEC <u>34</u> TWP <u>18s</u> RNG <u>2E</u> E/W <u>4622</u> FSL Ft. from N/S Line of Section. (circle one) <u>677</u> FEL Ft. from E/W Line of Sec. (circle one) <u>Marion</u> County	
Date of Closure: <u>8/15/2011</u>		RECEIVED AUG 25 2011 KCC WICHITA	
Was an artificial liner used? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents: Plastic liner was used to line the pit.			
Abandonment procedure of pit: <u>The pit was lined with plastic liner, there was a very minimal amount of fluids in the pit and those fluids evaporated due to the extreme heat. It was not necessary to haul any fluids.</u> <u>The plastic liner was then removed and the pit was backfilled and restored to natural condition.</u>			
The undersigned hereby certifies that he/she is <u>Alan L. DeGood, President</u> for <u>American Energies Corporation</u> a duly authorized agent, that all information shown hereon is true and correct to the best of his knowledge and belief.			
		 Alan L. DeGood, President	
Subscribed and sworn to before me on this <u>24th</u> day of <u>August</u> 2011		 Melinda S. Wooten, Notary Public	
My Commission Expires: 3-12-12			