KCC OIL/GAS REGULATORY OFFICES

Date: <u>11/30/11</u>	District: <u>01</u>
	New Situation Lease Inspection
	Response to Request Complaint
	Follow-Up Field Report
Operator License No: 30742	API Well Number: 15-135-25,314-00-00
Op Name: Palomino Petroleum, Inc.	Spot: <u>SE-NW-NW-SE</u> Sec <u>25</u> Twp <u>18</u> S Rng <u>24</u> E / ✓ W
Address 1: 4924 SE 84th St.	2266 (2284) Feet from N/ S Line of Section
Address 2:	2103 (2094) Feet from Feet from E/W Line of Section
City: Newton	GPS: Lat: 38.45674 Long: 99.92441 Date: 11/30/11
State: Kansas Zip Code: <u>67114 -8827</u>	Lease Name: Maier Estate Well #: 1
Operator Phone #: (316) 799-1000	County: Ness
Reason for Investigation:	
Witness Alt.II	
Problem:	
None	
Persons Contacted:	
resons contacted.	
Findings:	
8-5/8"@202'W/150sxs cement TD@4379' 5-1/2"@4371'W/150sxs cement	d 1/4#fle cool 20/ co. 150vo to pit
Port Collar@1474-cemented with 125sxs-smo	d-1/4#110 Seai-2%cc 155xs to pit.
,	·
Action/Recommendations: Follow	Up Required Yes No Date:
None, Atl.II requirements have been met.	
	RECEIVED
	DEC 1 3 2011
	VCC MINITA
·	KCC WICHITA
Verification Sources:	Photos Taken:
▼ RBDMS KGS	TA Program
T-I Database District Files	Courthouse Michael Major
Other: RECEIVED	Michael Maier
Retain 1 Copy District Office Send 1 Copy to Conservation Division 2 2011	AST .
//,	Form:
KCC DODGE CITY	

Date: 11/30/11		_		: <u>U1</u>		cense #: 30/42	
Op Name: <u>30742</u>	•					8 S Rng <u>24 </u>	W
County: Ness	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	Lease N	ame: <u>Maier Es</u>	tate	Well #: <u>1</u>	
I.D. Sign Yes	No		ري.	Gas Venting	Yes No		127
	l						_
							•
Tank Battery Cond	lition			Pits	÷		
Condition: Good		ble Overflow	vino 🖺	L	ft: Annroy S	ize:ft. xft	
Condition.	Questional	ole Overnow	, mg	Tiulu Deptii.	п, дриох. 5	12C1C. A1	
Dita Injection Site	·		·····	Coltunator	Pipelines		
Pits, Injection Site	e			—		· <u> </u>	.⊠ N
Fluid Depth:	_it; Approx. S	Size:1	t. xtt.	Leaks Visi	ble: Y N	Tested for Leaks: Y	N
				<u>'</u> .			
Oil Spill Evidence				Flowing H	Holes		
					•		
	9						
Abandoned Well	Potential Poll	ution Problem	Yes No 🔄	TA Wells	S		
	:						
				Monitoria	ng Records		
Lease Cleanliness			କ୍ର				
Very Good S	atisfactory _	Poor Ver	y Bad				
SWD/ER Injection Well	Yes	No	Ness 🖻	Gauge Conne	ections Yes No		6
Permit #: Pr				_		; C/SP Annulus:	_
Permit #:P						; C/SP Annulus:	
Permit #:Pi	•					; C/SP Annulus:	
Permit #: Pr						; C/SP Annulus:	
	*				· · · · · · · · · · · · · · · · · · ·		
API	Footages	Spot	GPS	Well	#	Well	
Number	4	Location	G15		"	Status	
15-135-25,314-00-00	2284FSL	SE NIM NIM SE	38.45674-99.92	2441 1	New well, Alt,II co	amploted	
13-133-23,314-00-00	20341 LL	SL-IVV-IVV-SL	50.45014-99.92	24411	INEW Well, Alt, II Co	Jilipieted	
						· · · · · · · · · · · · · · · · · · ·	
1117	ja.						
, 411, 05	19						
3136 6	1						
ومو يصوره	 g.+↑,				,		
		,					
		1 3 ·				, defende	
			·				

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: