

# KCC OIL/GAS REGULATORY OFFICES

Date: 12/08/11

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-25,319-00-00

Op Name: American Warrior

Spot: C-E/2-W/2-SW Sec 11 Twp 20 S Rng 24  E /  W

Address 1: P.O. Box 399

1450 (1467) Feet from  N /  S Line of Section

Address 2: P.O. Box 783188

.950 (966) Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.32382 Long: 99.94904 Date: 12/8/11

State: Kansas Zip Code: 67846 -0399

Lease Name: Petersilie Well #: 3-11

Operator Phone #: (620) 587-3224

County: Ness

**Reason for Investigation:**

Witness Alt.II

**Problem:**

None, cement circulated to surface

**Persons Contacted:**

**Findings:**

8-5/8" @776 W/150sxs cement  
TD @ 4520'  
5-1/2" @ 4515'W/175sxs cement  
Port Collar @ 1603' cemented with 120sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

**Action/Recommendations:**

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met

**RECEIVED**  
**DEC 23 2011**  
**KCC WICHITA**

**Verification Sources:**

Photos Taken: \_\_\_\_\_

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____		

**RECEIVED**

By: Michael Maier 

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

DEC 22 2011  
**KCC DODGE CITY**

Form: 02/22/2008

Date: 12/08/11

District: 01

License #: 4058

Op Name: 4058

Spot: C-E/2-W/2-SW Sec 11 Twp 20 S Rng 24  E  W

County: Ness

Lease Name: Petersilie Well #: 3-11

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.319-00-00	1467FSL 966FWL	C-E/2-W/2-SW	38.32382-99.94904	3-11	New well, Alt. II completed