## KCC OIL/GAS REGULATORY OFFICES

Date: <u>12/14/11</u>	District: <u>01</u>
	New Situation Lease Inspection
•	Response to Request Complaint
	Follow-Up Field Report
Operator License No: <u>5144</u>	API Well Number: <u>15-135-25,315-00-00</u>
Op Name: Mull Drilling Company, Inc.	Spot: <u>W/2-SW</u> Sec <u>6</u> Twp <u>16</u> S Rng <u>22</u>
Address 1: 1700 N Waterfront Pkwy	1320 (1333) Feet from N/ S Line of Section
Address 2: Bldg. 1200	660 (640) Feet from F / W Line of Section
City: Wichita	GPS: Lat: 38.68682 Long: 99.80419 Date: 12/14/11
State: Kansas Zip Code: 67206 -6637	Lease Name: KWT Well #: 1-6
Operator Phone #: (316) 264-6365	County: Ness
Reason for Investigation:	1
Witness Alt.II	
Problem:	
None, cement circulated to surface	
,	
	· · · · · · · · · · · · · · · · · · ·
Persons Contacted:	. 1
	<u> </u>
Findings:	
8-5/8" @ 221' W/165sxs cement	
TD @ 4490'	
5-1/2" @ 4479' W/175sxs cement	1.4/4#
Port Collar @ 1777' cement with 160sxs-smo	d-1/4# flo seal-2%cc-20sxs went to pit
Action/Recommendations: Follow	w Up Required ✓ Yes No 🖸 Date:
Alt.II requirements have been met.	
	RECEIVED
	DEC 2 3 2011
	KCC WICHITA
Verification Sources:	Photos Taken:
RBDMS KGS	TA Program
	Courthouse By: Michael Maier
Other:	
Retain 1 Copy District Office DEC 2 2 2011	- Ale
Send 1 Copy to Conservation Division  KCC DODGE CITY	Form: <u>02/22/2008</u>

Pate: 12/14/11			District:	01		Lic		
Op Name: <u>5144</u>			Spot: <u>W/</u>	Spot: <u>W/2-SW</u>		6 Twp <u>16</u>	S Rng <u>22</u>	E
County: Ness			Lease Nai	me: <u>KWT</u>			Well #: <u>1-</u>	6
I.D. Sign Yes	No		ত	Gas Venting	g Yes [	No		<b>5</b>
Tank Battery Cond	ition	THE CONTRACT OF THE CONTRACT O	,	Pits				
Condition: Good		ole Overflow	ing 🖆	Fluid Depth	1:	_ft; Approx. Si:	ze:f	t. xft.
Pits, Injection Site Fluid Depth:	_ft; Approx. S	Size:ft	. xft.		er Pipelines sible: Y	N	Tested for Lea	ks: Y N
Oil Spill Evidence				Flowing	Holes			
Abandoned Well	Potential Polli	ution Problem	Yes No	TA We	lls			
Lease Cleanliness Very Good S	atisfactory	Poor Very	্চ y Bad	Monitor	ring Records	6		
	ressure – Actu	al:psi; Aut al:psi; Aut al:psi; Aut	thorized: psi	Tubing: Tubing: Tubing:	; T ; T ; T	/C Annulus:	; C/SP A	Annulus:Annulus:Annulus:Annulus:
API Number	Footages	Spot Location	GPS	We	11#		Well Status	· <del></del>
<u>15-135-25,315-00-00</u>	1333FSL 00 640FWL W/2-SW 38.68682-99		38.68682-99.80	419 1-6	New	New well, Alt.II completed		
		ş	1 11 1 2 2					
· · · · · · · · · · · · · · · · · · ·		¥	*					
· · · · · · · · · · · · · · · · · · ·						•		·