

KCC OIL/GAS REGULATORY OFFICES

Date: 1-13-2012

District: 1

Case #: NH

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 32204  
 Op Name: Redland Res. Inc  
 Address 1: 6001 NW 23<sup>rd</sup> St.  
 Address 2: \_\_\_\_\_  
 City: Oklahoma, OK  
 State: ok Zip Code: 73127-1253  
 Operator Phone #: 405-789-7104

API Well Number: 15-083-21,730-0000  
 Spot: S10 S10 SW NW Sec 30 Twp 23 S Rng 24  E /  W  
2549 Feet from  N /  S Line of Section  
274 Feet from  E /  W Line of Section  
 GPS: Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Date: \_\_\_\_\_  
 Lease Name: Libby Well #: 30-5  
 County: Hodgeman

Reason for Investigation:

Complete Act II reworking

Problem:

NH

Persons Contacted:

DAVID HIDEMAN w/ Redland.

Findings:

898 @ 218 w/1705x  
4 1/2" e 4900 w/1755x  
DV coal @ 1363 w/ 2405x (Did not circulate)  
New Bond Log TOC @ 300±  
1-12-12 - Tied on 898x4 1/2" annular pumped 555x5. S.I @  
500 H's.  
A

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Act II has been completed.

**RECEIVED**  
**JAN 17 2012**  
**KCC WICHITA**

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Steve Dunbar

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_

Date: \_\_\_\_\_

District: \_\_\_\_\_

License #: \_\_\_\_\_

Op Name: \_\_\_\_\_

Spot: \_\_\_\_\_ Sec \_\_\_\_\_ Twp \_\_\_\_\_ S, Rng \_\_\_\_\_ E \_\_\_\_\_ W

County: \_\_\_\_\_

Lease Name: \_\_\_\_\_ Well #: \_\_\_\_\_

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness

Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_