## KCC OIL/GAS REGULATORY OFFICES

Date: 01/04/12	District: <u>01</u>
	New Situation Lease Inspection RECEIVED
	Response to Request Complaint
	Follow-Up Field Report JAN 2 5 2012
Operator License No: 7775	API Well Number: 15-101-22,333-00-00 KCC WICHITA
Op Name: Wilton Petroleum, Inc	Spot: SW-NE-SE Sec 13 Twp 16 S Rng 30 E / W
•	
Address 1: P.O. Box 391  Address 2:	
	4/4/40
City: Canton State: Kansas Zip Code: 67428 -	
Operator Phone #: (620) 628-4466	County: Lane
Reason for Investigation:	
Witness Atl.II	
Problem:	
None	
Persons Contacted:	
	·
Findings:	
8-5/8"@220'W/160sxs cement	
TD @ 4500'	
5-1/2"@4500W/125sxs cement	1 4 / 4 ft = 00/ == 00 == 45 mit
Port Collar @ 2483' cemented with 185sxs-	-sma-1/4 110-2%cc-20sxs to pit
	·
Action/Recommendations: Fol	llow Up Required Yes No 🔄 Date:
None, Atl.II requirements have been met.	
·	
	·
Verification Sources:	Photos Taken:
RBDMS KGS	TA Program
T-I Database District Files	Courthouse By:
Other:	Michael Maier
Retain 1 Copy District Office JAN 2 0 2012	
Send 1 Copy to Conservation Division	Form:
KCC DODGE CITY	

Date: 01/04/12			District	District: <u>01</u>		License #: <u>7775</u>		
Op Name: <u>7775</u>			Spot: <u>S</u> \	W-NE-	SE	Sec <u>13</u> Twp <u>1</u>	6 S Rng 30	] E 🕢 W
County: <u>Lane</u>	Lease Na	ame: <u>M</u>	agie		Well #: <u>3</u>			
I.D. Sign Yes	No		15)	Gas	Venting [	Yes No		<u>*</u> 0
Tank Battery Condition  Condition: Good Questionable Overflowing			wing 🔊	-	its	ft; Approx. S		
Condition. [ Good [	Questiona	pie Over iio.	wing	Fluid	г Берии:	tt; Approx. 5	ze:nt. x	rt.
Pits, Injection Site				□s	altwater P	ripelines	<u></u>	<b>6</b>
Fluid Depth:	_ft; Approx.	Size:	ft. xft.	Le	aks Visible	e: Y N	Tested for Leaks:	Y N
Oil Spill Evidence				F	lowing Ho	les		
Abandoned Well	Potential Poll	lution Problem	Yes No in		TA Wells			
					lonitoring	Records		
Lease Cleanliness Very Good S	atisfactory _	Poor Ver	y Bad					
SWD/ER Injection Well	Yes _	] No	Lane	Gaug	e Connect	ions Yes No		10
Permit #:P				Tubi	ng:	; T/C Annulus:	; C/SP Annulus:	·
Permit #: Pi						; T/C Annulus:		
Permit #:Pi		•				; T/C Annulus:		
Permit #:Pi	ressure – Actu	al: psi; Au	thorized: psi	Tubii	1g:	; T/C Annulus:	; C/SP Annulus:	:
API Number	Footages	Spot Location	GPS		Well#		Well Status	
<u>15-101-22,333-00-00</u>	1777FSL 866FEL	SW-NE-SE	38.66143-100.5	8029	3	New well, Alt,II co	mpleted	
				·.				
							<del> </del>	