To:	APLNUMBER	15-001-21057-00-0
STATE CORPORATION COMMISSION	NE	Sec/Twp/Rge <u>16 - 26S - 21E</u>
Wichita State Office Bldg PLUGGING SECTION	4697	feet from south section line
130 S. Market, Room 2078 Wichita, Kansas 67202	1970	feet from east section line
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	Daniels MUR69-0 (32)
Operator License # 101	County	Allen
Operator: State of Kansas	Well Total Depth	
Name &	Production Pipe:	2 Size Feet700
Address	Surface Casing:	Size Feet
AB oil well XXXX Gas Well SWD Wel	ll/ Input Well	D & A
Other well as hereinafter indicated:		
Plugging Contractor: Kepley Well Service, LLC	· · · · · · · · · · · · · · · · · · ·	Lic. # 33749
Address: 19245 Ford Road Chanute, KS 66720		
Company to plug at: Hour:Day:	23	Month: <u>11</u> 2009
Plugging proposal received from: Mike Kepley		
Company Name: Kepley Well Service, LLC		Phone: 620-431-9212
Were: Clean out and prepare well for plugging and	circulate cement to	surface
- Fragging and	Circulate Content to	- Curiaco.
Plugging Proposal Re		Ryan M. Duling
Plugging Proposal Re	eceived by: _Part	Ryan M. Duling TECHNICIAN
Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day:	eceived by: _Part _23	Ryan M. Duling TECHNICIAN None XXXX
Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day:	eceived by: _Part23 2" casing with a ba	Ryan M. Duling TECHNICIAN None XXXX Month: 11 2009 ackhoe approximately 4' and found
Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the	eceived by: Part 23 2" casing with a ba	Ryan M. Duling TECHNICIAN None XXXX Month: 11 2009 ackhoe approximately 4' and found forated nipple. Ran 1" pipe inside
Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the the casing surrounded by cement. Pulled 700' of 1" pipe	eceived by: Part 23 2" casing with a base and pump with percasing to 698'. Circ	Ryan M. Duling TECHNICIAN None XXXX Month: 11 2009 ackhoe approximately 4' and found forated nipple. Ran 1" pipe inside
Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the the casing surrounded by cement. Pulled 700' of 1" pipe of 2" casing to 695'. Washed 1" pipe down inside of 2"	Part 23 2" casing with a base and pump with percentage to 698'. Circulated cerentage and compared to the company of the compa	Ryan M. Duling TECHNICIAN None XXXX Month: 11 2009 ackhoe approximately 4' and found forated nipple. Ran 1" pipe inside sulated cement through 1" pipe ment through 1" pipe from 350'
Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the the casing surrounded by cement. Pulled 700' of 1" pipe of 2" casing to 695'. Washed 1" pipe down inside of 2" cinside 2" casing from 698' to surface. Pulled 350' of 1" pipe down inside of 2" cinside 2" casing from 698' to surface.	Part 23 2" casing with a bas and pump with percasing to 698'. Circulated cereasing with with the company of th	Ryan M. Duling TECHNICIAN None XXXX Month: 11 2009 ackhoe approximately 4' and found forated nipple. Ran 1" pipe inside sulated cement through 1" pipe ment through 1" pipe from 350' th cement and shut in at 350
Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the the casing surrounded by cement. Pulled 700' of 1" pipe of 2" casing to 695'. Washed 1" pipe down inside of 2" of inside 2" casing from 698' to surface. Pulled 350' of 1" pipe to surface. Pulled the rest of the 1" pipe out of the hole.	Part 23 2" casing with a bas and pump with percasing to 698'. Circulated cereasing with with the company of th	Ryan M. Duling TECHNICIAN None XXXX Month: 11 2009 ackhoe approximately 4' and found forated nipple. Ran 1" pipe inside sulated cement through 1" pipe ment through 1" pipe from 350' th cement and shut in at 350
Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the the casing surrounded by cement. Pulled 700' of 1" pipe of 2" casing to 695'. Washed 1" pipe down inside of 2" of inside 2" casing from 698' to surface. Pulled 350' of 1" pipe to surface. Pulled the rest of the 1" pipe out of the hole. psi. A total of 27 sacks of portland cement was used to	Part 23 2" casing with a base and pump with percasing to 698'. Circulated ceres Squeezed well with plug this well. The	Ryan M. Duling TECHNICIAN None XXXX Month: 11 2009 ackhoe approximately 4' and found forated nipple. Ran 1" pipe inside culated cement through 1" pipe ment through 1" pipe from 350' th cement and shut in at 350 well was cut of below surface
Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the the casing surrounded by cement. Pulled 700' of 1" pipe of 2" casing to 695'. Washed 1" pipe down inside of 2" of inside 2" casing from 698' to surface. Pulled 350' of 1" pi to surface. Pulled the rest of the 1" pipe out of the hole. psi. A total of 27 sacks of portland cement was used to and the location was restored. Remarks: Contract #12391 Control #20100001-069	Part 23 2" casing with a base and pump with percasing to 698'. Circulated ceres Squeezed well with plug this well. The	Ryan M. Duling TECHNICIAN None XXXX Month: 11 2009 ackhoe approximately 4' and found forated nipple. Ran 1" pipe inside sulated cement through 1" pipe ment through 1" pipe from 350' th cement and shut in at 350 well was cut of below surface 21935 37.78976RECEIVED