To:		API NUMBER	15-001-	<u>0308</u>	6-0	<u> </u>
STATE CORPORATION COMMISSION		SESENE	Sec/Twp/Rge	16 - 26S	- 21E	
Wichita State Office Bldg PLUGGING SECTION		3090 feet from south section line				
130 S. Market, Room 2078 Wichita, Kansas 67202		602	feet from ea	ast section	line	
TECHNICIAN'S PLUGGING REPORT		Lease/Well#	Daniels MU	JR27-P	-	
Operator License # 101		County	Allen			
Operator: State of Kansas	_	Well Total Depth		32	2 <u>5</u> feet	
Name &	-	Production Pipe:		_Size Fee	et	
Address	_	Surface Casing:	8	8 Size Fee	et	
AB oil well XXXX Gas Well	SWD Well/	Input Well		_D&A		
Other well as hereinafter indicated:		***************************************				
Plugging Contractor: Kepley Well Service, L	LC			_Lic. #		33749
Address: 19245 Ford Road Chanute, KS 6	6720					···
Company to plug at: Hour:	Day:	19	Month:		7	2010
	ev					
Plugging proposal received from: Mike Keple						
Plugging proposal received from: Mike Keple Company Name: Kepley Well Service, L	<u>* </u>		Phone:	620-431-	-9212	
	.LC	circulate cement to	•	620-431-	-9212	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu	LC ogging and c		surface.			
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P	.LC		surface.	620-431- yan M. Duli	ing	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All	LC ogging and c	ceived by:	surface.	yan M. Duli	ing	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All	LC ogging and c	ceived by:	surface.	yan M. Duli TECHNICI/	ing	2010
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down	eroposal Rec	ceived by: Part 19 urface casing. Set	Surface. Ry XXXX Month: up drilling right	yan M. Duli TECHNICI/ None None	ing AN 7	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down 8" surface casing to 325'. Ran 1" pipe insided	eroposal Reconstruction find 8" surficients	ceived by: Part 19 urface casing. Set	Surface. Ry XXXX Month: up drilling right.	yan M. Duli TECHNICI/ None None g. Drilled i	ing AN 7 inside t	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down 8" surface casing to 325'. Ran 1" pipe insided the 1" pipe from 325' to surface. Pulled 1" pipe	eroposal Reconstruction find 8" surficients	ceived by: Part 19 urface casing. Set	Surface. Ry XXXX Month: up drilling right.	yan M. Duli TECHNICI/ None None g. Drilled i	ing AN 7 inside t	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour:	eroposal Reconstruction find 8" surficients	ceived by: Part 19 urface casing. Set	Surface. Ry XXXX Month: up drilling right.	yan M. Duli TECHNICI/ None None g. Drilled i	ing AN 7 inside t	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down 8" surface casing to 325'. Ran 1" pipe insided the 1" pipe from 325' to surface. Pulled 1" pipe	eroposal Reconstruction find 8" surficients	ceived by: Part 19 urface casing. Set	Surface. Ry XXXX Month: up drilling right.	yan M. Duli TECHNICI/ None None g. Drilled i	ing AN 7 inside t	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down 8" surface casing to 325'. Ran 1" pipe insided the 1" pipe from 325' to surface. Pulled 1" pipe	eroposal Reconstruction find 8" surficients	ceived by: Part 19 urface casing. Set	Surface. Ry XXXX Month: up drilling right.	yan M. Duli TECHNICI/ None None g. Drilled i	ing AN 7 inside t	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down 8" surface casing to 325'. Ran 1" pipe insided the 1" pipe from 325' to surface. Pulled 1" pipe below surface and the site was restored.	gging and congress of the second seco	ceived by: Part 19 Inface casing. Set face casing to 325' 8" casing off with	XXXX Month: up drilling right Circulated cement. The	yan M. Duli TECHNICI/ None g. Drilled i cement th e well was	ing AN 7 Inside the cut off	
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down 8" surface casing to 325'. Ran 1" pipe insided the 1" pipe from 325' to surface. Pulled 1" pipe below surface and the site was restored. Remarks: Contract #12391 Control #20100	Day: to find 8" surfice. Topped	ceived by: Part 19 Inface casing. Set face casing to 325' 8" casing off with	XXXX Month: up drilling right Circulated cement. The	yan M. Duli TECHNICI/ None None g. Drilled i	ing AN 7 Inside the rough cut off	ne
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down 8" surface casing to 325'. Ran 1" pipe insided the 1" pipe from 325' to surface. Pulled 1" pipe below surface and the site was restored. Remarks: Contract #12391 Control #20100 (If additional description is nearly surface).	Day: to find 8" surfice. Topped	ceived by: Part 19 Inface casing. Set face casing to 325' 8" casing off with	XXXX Month: up drilling right Circulated cement. The	yan M. Duli TECHNICI/ None g. Drilled i cement th e well was	ing AN 7 Inside the rough cut off	ne
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down 8" surface casing to 325'. Ran 1" pipe insided the 1" pipe from 325' to surface. Pulled 1" pipe below surface and the site was restored. Remarks: Contract #12391 Control #20100	Day: to find 8" surfice. Topped	ceived by: Part 19 Inface casing. Set face casing to 325' 8" casing off with	XXXX Month: up drilling right Circulated cement. The	yan M. Duli TECHNICI/ None g. Drilled i cement th e well was	ing AN 7 Inside the rough cut off	ne
Company Name: Kepley Well Service, L Were: Clean out and prepare well for plu Plugging P Plugging attended by Agent: All Operations Completed: Hour: Actual Plugging Report: Dug down 8" surface casing to 325'. Ran 1" pipe insided the 1" pipe from 325' to surface. Pulled 1" pipe below surface and the site was restored. Remarks: Contract #12391 Control #20100 (If additional description is nearly surface).	Day: to find 8" surfice. Topped	ceived by: Part 19 Inface casing. Set face casing to 325' 8" casing off with	XXXX Month: up drilling right Circulated cement. The	yan M. Duli TECHNICI/ None g. Drilled i cement th e well was	ing AN 7 inside the cut off NAS	