To:		API NUMBER	15-001	1-2121	<u> 1 - 00-0</u>	
STATE CORPORATION COMMIS	SSION	NESENE	Sec/Twp/Rge	16 - 26S - 21E		
Wichita State Office Bldg PLUGGING SECTION		3360	3363 feet from south section line			
130 S. Market, Room 2078 Wichita, Kansas 67202		240	0 feet from ea	st section line	•	
TECHNICIAN'S PLUGGING REP	ORT	Lease/Well#	Daniels MU	JR08- O (/4	<u> </u>	
Operator License #101		County	Allen		<u></u>	
Operator: State of Kansas		Well Total Depth	ı	695_fee	et	
Name &		Production Pipe:	:2.875	Size Feet	695	
Address	.	Surface Casing:		_Size Feet		
AB oil well XXXX Gas Well	swd \	Well/ Input Well		_D&A		
Other well as hereinafter indicated	: :					
Plugging Contractor: Kepley We	Il Service, LLC			_Lic. #	33749	
Address: 19245 Ford Road Cha	anute, KS 66720					
Company to plug at: Hour:	Day:		2 Month:	12	2009	
	Mike Kenley					
Plugging proposal received from:	WINC Repley					
	Il Service, LLC	and circulate cement t	Phone: o surface.	620-431-9212		
Company Name: Kepley We	Il Service, LLC	and circulate cement to	_	620-431-9212		
Company Name: Kepley We	Il Service, LLC		o surface.	van M. Duling		
Company Name: Kepley We	Il Service, LLC well for plugging a	I Received by:	o surface.			
Company Name: <u>Kepley We</u> Were: <u>Clean out and prepare</u>	Il Service, LLC well for plugging a	I Received by:	o surface.	van M. Duling TECHNICIAN	2009	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent:	Plugging Proposa All XXX Day:	I Received by:	Ry Month:	van M. Duling TECHNICIAN None	2009	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent: Operations Completed: Hour:	Plugging Proposa All XXX Day:	I Received by: X Part the 2.875" casing with	Ry Month: h the backhoe	ran M. Duling TECHNICIAN None 12 2 4' and found th	2009	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report:	Plugging Proposa All XXX Day: Dug down beside ashed 1" pipe down	I Received by: X Part the 2.875" casing with the inside of 2.875"	Ry Month: h the backhoe casing to 690	van M. Duling TECHNICIAN None 12 2 4' and found the	2009 ne	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: casing surrounded by cement. W	Plugging Proposa All XXX Day: Dug down beside ashed 1" pipe down casing to 695'. Ci	I Received by: X Part the 2.875" casing with the inside of 2.875"	Ry Month: h the backhoe casing to 690 ugh the 1" pipe	van M. Duling TECHNICIAN None 12 4' and found the down the inside	2009 ne	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: casing surrounded by cement. W pipe down the inside of the 2.875"	Plugging Proposa All XXX Day: Dug down beside ashed 1" pipe down beside ashed 1" pipe down beside auriace. Pulled 300	I Received by: X Part the 2.875" casing with n the inside of 2.875" irculated cement throu	Ry Month: h the backhoe casing to 690 ugh the 1" pipe	van M. Duling TECHNICIAN None 12 2 4' and found the down the inside the 1" pipe	2009 ne	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: casing surrounded by cement. W pipe down the inside of the 2.875" of the 2.875" casing from 695' to s	Plugging Proposa All XXX Day: Dug down beside ashed 1" pipe down casing to 695'. Citatrace. Pulled 300 to surface. Pulled	I Received by: X Part the 2.875" casing with n the inside of 2.875" irculated cement through of 1" pipe. Circulated the remaining 1" pipe	Ry 2 Month: h the backhoe casing to 690 ugh the 1" pipe ed cement thro e. Topped the	van M. Duling TECHNICIAN None 12 2 4' and found the down the inside the 1" pipe 2.875" casing	2009 ne	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: casing surrounded by cement. W pipe down the inside of the 2.875" of the 2.875" casing from 695' to s inside the 2.875" casing from 350"	Plugging Proposa All XXX Day: Dug down beside ashed 1" pipe down casing to 695'. Citatrface. Pulled 300 to surface. Pulled of portland cement	I Received by: X Part the 2.875" casing with n the inside of 2.875" irculated cement through of 1" pipe. Circulated the remaining 1" pipe	Ry 2 Month: h the backhoe casing to 690 ugh the 1" pipe ed cement thro e. Topped the	van M. Duling TECHNICIAN None 12 2 4' and found the down the inside the 1" pipe 2.875" casing	2009 ne	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: casing surrounded by cement. W pipe down the inside of the 2.875" of the 2.875" casing from 695' to s inside the 2.875" casing from 350' with cement. A total of 27 sacks of surface and the site was restored. Remarks: Contract #12391 Co	Plugging Proposa All XXX Day: Dug down beside ashed 1" pipe down casing to 695'. Cito surface. Pulled 300 to surface. Pulled of portland cement introl #20100001-00	I Received by: X Part the 2.875" casing with n the inside of 2.875" irculated cement through of 1" pipe. Circulated I the remaining 1" pipe was used to plug this	Ry 2 Month: h the backhoe casing to 690 ugh the 1" pipe ed cement thro e. Topped the well. The we	van M. Duling TECHNICIAN None 12 2 4' and found the down the inside the 1" pipe 2.875" casing	2009 ne de	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: casing surrounded by cement. W pipe down the inside of the 2.875" of the 2.875" casing from 695' to s inside the 2.875" casing from 350' with cement. A total of 27 sacks of surface and the site was restored. Remarks: Contract #12391 Co	Plugging Proposa All XXX Day: Dug down beside ashed 1" pipe down casing to 695'. Cito surface. Pulled 300 to surface. Pulled of portland cement introl #20100001-00	I Received by: X Part the 2.875" casing with n the inside of 2.875" irculated cement throu o' of 1" pipe. Circulated I the remaining 1" pipe was used to plug this	Ry 2 Month: h the backhoe casing to 690 ugh the 1" pipe ed cement thro e. Topped the well. The we	ran M. Duling TECHNICIAN None 12 4' and found the down the inside ough the 1" pipe 2.875" casing	2009 ne de	
Company Name: Kepley We Were: Clean out and prepare Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: casing surrounded by cement. W pipe down the inside of the 2.875" of the 2.875" casing from 695' to s inside the 2.875" casing from 350' with cement. A total of 27 sacks of surface and the site was restored. Remarks: Contract #12391 Co (If additional of CPS 4-14-09 NA)	Plugging Proposa All XXX Day: Dug down beside ashed 1" pipe down casing to 695'. Cito surface. Pulled 300 to surface. Pulled of portland cement introl #20100001-00 description is necessary	I Received by: X Part the 2.875" casing with n the inside of 2.875" irculated cement through of 1" pipe. Circulated I the remaining 1" pipe was used to plug this	Ry 2 Month: h the backhoe casing to 690 ugh the 1" pipe ed cement thro e. Topped the well. The we	ran M. Duling TECHNICIAN None 12 4' and found the down the inside ough the 1" pipe 2.875" casing	2009 ne de	