To:	APINUMBER	15-001-21034-00-0	00
STATE CORPORATION COMMISSION	WWWE	Sec/Twp/Rge 16 - 26S - 21E	
Wichita State Office Bldg PLUGGING SECTION	3396	feet from south section line	
130 S. Market, Room 2078 Wichita, Kansas 67202	1534	feet from east section line	
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	Daniels MUR53-O (17)	
Operator License #101	County	Allen	
Operator: State of Kansas	Well Total Depth	665_ feet	
Name &	Production Pipe:	2.875 Size Feet 665	
Address	Surface Casing:	Size Feet	
AB oil well XXXX Gas Well SWD We	ell/ Input Well	D & A	
Other well as hereinafter indicated:			
Plugging Contractor: Kepley Well Service, LLC		Lic. # 33749	
Address: 19245 Ford Road Chanute, KS 66720			
Company to plug at: Hour: Day:	13	Month:11 2009	
Plugging proposal received from: Mike Kepley			
Company Name: Kepley Well Service, LLC		Phone: 620-431-9212	
Were: Clean out and prepare well for plugging and	d circulate cement to	a surface	
	a on outdo outnott to	Surrace.	
Plugging Proposal R	Received by:	Ryan M. Duling TECHNICIAN	
Plugging Proposal R Plugging attended by Agent: All	Received by:	Ryan M. Duling TECHNICIAN None XXXX	
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour:Day:	Received by: Part	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009	
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the	Received by:Part13 e 2.875" casing with	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009  a backhoe approximatley 4' and	
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the found casing surrounded by cement. Pulled 50' of 1" w	Received by: Part 13 e 2.875" casing with	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009 a backhoe approximatley 4' and 2.875" casing. Ran 1" pipe	
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the found casing surrounded by cement. Pulled 50' of 1" we down 2.875" casing to 660'. Washed 1" pipe down to 6	Received by: Part 13 e 2.875" casing with with packer out of the	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009 a backhoe approximatley 4' and 2.875" casing. Ran 1" pipe nent through 1" pipe from 665' to	
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the found casing surrounded by cement. Pulled 50' of 1" w down 2.875" casing to 660'. Washed 1" pipe down to 6 surface. Pulled 325' of 1" pipe. Circulated cement from	Received by:  Part  13 e 2.875" casing with vith packer out of the 665'. Circulated cerm	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009  a backhoe approximatley 4' and  2.875" casing. Ran 1" pipe nent through 1" pipe from 665' to  ulled the remaining 300' of 1"	
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the found casing surrounded by cement. Pulled 50' of 1" w down 2.875" casing to 660'. Washed 1" pipe down to 6 surface. Pulled 325' of 1" pipe. Circulated cement from pipe and topped off the well with cement. A total of 25	Received by:  Part  13 e 2.875" casing with vith packer out of the 665'. Circulated cerm 300' to surface. Packs of portland ce	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009  a backhoe approximatley 4' and  2.875" casing. Ran 1" pipe nent through 1" pipe from 665' to  ulled the remaining 300' of 1"	
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the found casing surrounded by cement. Pulled 50' of 1" w down 2.875" casing to 660'. Washed 1" pipe down to 6 surface. Pulled 325' of 1" pipe. Circulated cement from	Part  Part  13 e 2.875" casing with vith packer out of the 665'. Circulated cerm 300' to surface. Packs of portland cerm was restored.	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009  a backhoe approximatley 4' and 2.875" casing. Ran 1" pipe nent through 1" pipe from 665' to ulted the remaining 300' of 1" ement was used to plug this	
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the found casing surrounded by cement. Pulled 50' of 1" w down 2.875" casing to 660'. Washed 1" pipe down to 6 surface. Pulled 325' of 1" pipe. Circulated cement from pipe and topped off the well with cement. A total of 25	Received by:  Part  13 e 2.875" casing with vith packer out of the 665'. Circulated cerm 300' to surface. Packs of portland cent was restored.	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009 a backhoe approximatley 4' and 2.875" casing. Ran 1" pipe nent through 1" pipe from 665' to ulled the remaining 300' of 1" ement was used to plug this	ΞD
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the found casing surrounded by cement. Pulled 50' of 1" w down 2.875" casing to 660'. Washed 1" pipe down to 6 surface. Pulled 325' of 1" pipe. Circulated cement from pipe and topped off the well with cement. A total of 25 well. The well was cut off below grade and the location Remarks: Contract #12391 Control#20100001-053	Received by:  Part  13 e 2.875" casing with vith packer out of the 665'. Circulated cerm 300' to surface. Packs of portland cent was restored.  95.11698 GPS 4-15-	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009 a backhoe approximatley 4' and 2.875" casing. Ran 1" pipe nent through 1" pipe from 665' to ulled the remaining 300' of 1" ement was used to plug this	
Plugging Proposal R Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: Dug down beside the found casing surrounded by cement. Pulled 50' of 1" w down 2.875" casing to 660'. Washed 1" pipe down to 6 surface. Pulled 325' of 1" pipe. Circulated cement from pipe and topped off the well with cement. A total of 25 well. The well was cut off below grade and the location	Received by:  Part  13 e 2.875" casing with vith packer out of the 665'. Circulated cerm 300' to surface. Packs of portland cent was restored.  95.11698 GPS 4-15-	Ryan M. Duling  TECHNICIAN None XXXX  Month: 11 2009 a backhoe approximatley 4' and 2.875" casing. Ran 1" pipe nent through 1" pipe from 665' to ulled the remaining 300' of 1" ement was used to plug this	2011