STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION CONSERVATION DIVISION - PLUGGING REPORT 3960 feet from S section I 3960 feet from E section I 396	Ŷo:	¹ 020108	API NUMBER 15- 093	-20,832
200 COLORADO DERRY BUILDING MICHITA, KARSAS 67202 TECHNICIAN'S PLUGGING REPORT 3960 feet from E section I Operator License / 4315 Lease Name Adamson Neil / 1 Operator: Brazos Petroleum Company			C NW/4 . SEC. 1	. T 22 S. R 36 W
TECHNICIAN'S PLUGGING REPORT 3960 feet from E section 1	200 COLOR	ADO DERBY BUILDING		
Operator License / 4315 Operator: Brazos Petroleum Company County Kearny Node Address P.O. Box 1782 Midland, TX 79702 Conductor Pipe: Size Foot Surface Casing: Size 8 5/8 feet 225 Abandoned Oli Weil Gas Weil X Input Weil SWD Weil O&A Other well as hereinafter indicated Plugging Contractor Dowell Schlumberger License Number Address Ulysses, KS Company to plug af: Hour: 11:10 a.m.pay: 7 Month: 12 Year:1987 Plugging proposal received from (company name) Dowell Schlumberger (company name) Dowell Schlumberger (company name) Dowell Schlumberger (company and 3196' PBTD 3154' Perfs - none Elevation 3205.5'GL Ist plug circulate cement through thining from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug fillsammulus with econolight. Plugging Operations aftended by Agent7: All X Part None Operations Completed: Hour: 2:10 p.meay: 8 Nonth: 12 Year:1987 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. CONNERNAM:	•			•
Operator: Names Address P.O. Box 1782 Midland, TX 79702 Conductor Pipe: Size Surface Casing: Size 8 5/8 feet 225 Abandoned Oli Well Gas Well X input Well SND Well D&A Other well as hereinefter indicated Plugging Contractor Dowell Schlumberger License Number Address Ulysses, KS Company to plug at: Hour: 11:10 a.m.Day: 7 Honth: 12 Year:19 87 Plugging proposal received from (company name) Dowell Schlumberger (company name) Dowell Schlumberger were: 4½" at 3196' PBTD 3154' Perfs - none Elevation 3205.5'GL Ist plug circulate cement through tubing, 3rd plug fill 4½" after pulling tubing, 3rd plug fillammulus with econolight. Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.m.Bay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. STATE COMPORATION POMASENVAN: VICTUAL NO. COMASENVAN:				
Name& Address P.O. Box 1782 Well Total Depth 3200 f Midland, TX 79702 Conductor Pipe: Size feet	•			
Midland, TX 79702 Conductor Pipe: Size feet Surface Cesing: Size 8 5/8 feet 225 Abandoned Oli Well Gas Well X Input Well SWD Well D&A Other well as hereinefter indicated Plugging Contractor Dowell Schlumberger	Name&		County Kearny	104.00
Surface Casing: Size 8 5/8 feet 225 Abandoned Oil Weil Gas Weil X Input Weil SMD Weil D&A Other well as hereinafter indicated Plugging Contractor Dowell Schlumberger License Number Address Ulysses, KS Company to plug at: Hour: 11:10 a.m.oay: 7 Month: 12 Year:1987 Plugging proposal received from (company name) Dowell Schlumberger (phone) 316-356-127 were: 4½" at 3196' PBTD 3154' Perfs - none Elevation 3205.5'GL 1st plug circulate cement through thibing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug fillsamnulus with econolight. Plugging Operations attended by Agent7: All X Perf None Operations Completed: Hour: 2:10 p.m.ay: 8 Month: 12 Year:1987 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. **CONSERVAL*** **CONSERVAL** **	Address		Well Total Depth	feet
Abandoned Oll Well Gas Well X Input Well SWD Well D&A Other veil as hereinafter indicated Plugging Contractor Dowell Schlumberger License Number Address Ulysses, KS Company to plug at: Hour: 11:10 a.m.Day: 7 Month: 12 Year:1987 Plugging proposal received from (company name) Dowell Schlumberger (phone) 316-356-127 Were: 4½" at 3196' PETD 3154' Perfs - none Elevation 3205.5'GL 1st plug circulate cement through tubing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug fillamnulus with econolight. Plugging Proposal Received by Clenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Pert None Operations Completed: Hour: 2:10 p.meay: 8 Month: 12 Year:1987 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. CONSERVAL VICENARIONAL VICENARIO		Midland, TX 79702	Conductor Pipe: Siz	zefeet
Other veil as hereinafter indicated Plugging Contractor Dowell Schlumberger License Number Address Ulysses, KS Company to plug at: Hour: 11:10 a.m.Day: 7 Month: 12 Year:19.87 Plugging proposal received from (company name) Dowell Schlumberger (phone) 316-356-127 were: 4½" at 3196' PETD 3154' Perfs - none Elevation 3205.5'GL 1st plug circulate cement through tubing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug fillamnulus with econolight. Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.m.pay: 8 Month: 12 Year:19.87 ACTUAL Plugging REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. PLOSE (COMPORA) SCHOOL COMPORA (A.M.) VICTION OF A COMPORA (A.M.) VIC			Surface Casing: Si:	ze 8 5/8 feet 225
Plugging Contractor Dowell Schlumberger Address Ulysses, KS Company to plug at: Hour: 11:10 a.m.Day: 7 Month: 12 Year:1987 Plugging proposal received from (company name) Dowell Schlumberger (phone) 316-356-127 were: 4½" at 3196' PBTD 3154' Perfs - none Elevation 3205.5'GL Ist plug circulate cement through tubing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug filladmnulus with econolight. Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Perf None Operations Completed: Hour: 2:10 p.m.Bay: 8 Month: 12 Year:1987 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. STATE CORPORA* 13-10-8 COMSERVAN: USENTIAL PLUGGING RECORDING CEMENT 15 POWELL Schlumberger. No casing recovery.	Abandonéd	Oll Well Gas WellX	Input WellSI	WD WellD&A
Plugging Contractor Dowell Schlumberger Address Ulysses, KS Company to plug at: Hour: 11:10 a.m.Day: 7 Month: 12 Year:1987 Plugging proposal received from (company name) Dowell Schlumberger (phone) 316-356-127 Were: 4½" at 3196' PBTD 3154' Perfs - none Elevation 3205.5'GL Ist plug circulate cement through tubing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug fillamnulus with econolight. Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.m.bay: 8 Month: 12 Year:1987 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. STATE CORPORA* 13-10-8 CONSERVAN: Used Econolight cement by Dowell Schlumberger. No casing recovery.	Other wel	1 as hereinafter indicated		
Address_Ulysses, KS Company to plug at: Hour: 11:10 a.m.Day: 7 Month: 12 Year:1987 Plugging proposal received from (company name) Dowell Schlumberger (phone) 316-356-127 were: 4½" at 3196' PBTD 3154' Perfs - none Elevation 3205.5'GL lst plug circulate cement through tubing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug fillsamnulus with econolight. Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.m.bay: 8 Month: 12 Year:1987 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. COMSERVAL VICHARIAN Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.		· · · · · · · · · · · · · · · · · · ·		
Company to plug at: Hour: 11:10 a.m.Day: 7 Month: 12 Year:1987 Plugging proposal received from (company name) Dowell Schlumberger (phone) 316-356-127 were: 4½" at 3196' PBTD 3154' Perfs - none Elevation 3205.5'GL lst plug circulate cement through tubing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug fillaannulus with econolight. Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Pert None Operations Completed: Hour: 2:10 p.m.bay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. COMSERVAL LOCASERVAL COMSERVAL Remerks: Used Econolight cement by Dowell Schlumberger. No casing recovery.		•		
Plugging proposal received from (company name) Dowell Schlumberger (phone) 316-356-127 were: 4½" at 3196' PETD 3154' Perfs - none Elevation 3205.5'GL lst plug circulate cement through tubing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug filladinulus with econolight. Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.mbay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT lst plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. CONSERVAN (CONSERVAN)				2 Yangun 87
(company name) Dowell Schlumberger (phone) 316-356-127 were: 4½" at 3196' PBTD 3154' Perfs - none Elevation 3205.5'GL lst plug circulate cement through tubing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug filladmulus with econolight. Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.m.Bay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. STATE CORPORAT A CONSERVAL VICTUAL PLUGGING REPORT 1st Plug Circulated Cement No casing recovery.		· ·		• •
were: 4½" at 3196' PBTD 3154' Perfs - none Elevation 3205.5'GL lst plug circulate cement through tubing from 1519' to surface, 2nd plug fill 4½" after pulling tubing, 3rd plug fillamnulus with econolight. Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent7: All X Part None Operations Completed: Hour: 2:10 p.mbay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. SINCE CORPORAT A CONSERVAL Whenta have a converge to the conve		•		
St plug circulate cement through tubing from 1519' to surface,				
2nd plug fill 4½" after pulling tubing, 3rd plug fill=annulus with econolight. Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.mBay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. SINTE CORPORAT 10 - 10 - 8	were: 42	" at 3196' PBTD 3154' Perfs - nor	ne Elevation 3205.5'	GL
Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None	1st plug	circulate cement through tubing fro	om 1519' to surface,	
Plugging Proposal Received by Glenn Barlow (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.mpay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. SIATE CORPORAT 12 - No. 8	2nd plug	fill 4½" after pulling tubing,		
Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.mpay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 45" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. SIMPLE CORPORAT 10-10-85 CONSERVAL Wichita Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.	3rd plug	fill-annulus with econolight.		
Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.mpay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 45" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. SIMPE CORPORAT 18-10-8 CONSERVAL Wichita None CONSERVAL Wichita None Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.			** .	· · · · · · · · · · · · · · · · · · ·
Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 2:10 p.mbay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. STATE CORPORA CONSERVAL Wichita have Prichita have Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.	·	Plugging Propos	al Received by	Glenn Barlow
Operations Completed: Hour: 2:10 p.mpay: 8 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT lst plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. STATE CORPORAT CONSERVATION Wightin house Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.		:		·
ACTUAL PLUGGING REPORT 1st plug circulated cement through tubing from 1519-0', 2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. STATE CORPORAT CONSERVATION Wichia Marks: Used Econolight cement by Dowell Schlumberger. No casing recovery.				
2nd plug filled 4½" after pulling tubing, 3rd plug checked annulus and filled with 4½ barrels econolight. STATE CORPORAT 10-10-8 CONSERVATI Wichita human Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.	Operation	s Completed: Hour: $2:10 \text{ p.m}$ Day:	8 Month:	12 Year: 19 87
3rd plug checked annulus and filled with 4½ barrels econolight. SIGNE CORPORAT 10-16-8 CONSERVATI Wichita human Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.	ACTUAL PL	UGGING REPORT 1st plug circulated	cement through tubing	g from 1519-0',
CONSERVAL. Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.	2nd plug i	filled 45" after pulling tubing,		i
Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.	3rd plug o	checked annulus and filled with $4\frac{1}{2}$	barrels econolight.	OFFICE OF THE PARTY OF THE PART
Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.			SIA	- 000003AT
Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.			, C	hada a cor
Remarks: Used Econolight cement by Dowell Schlumberger. No casing recovery.	:			weed the same of t
(If additional description is necessary, use BACK of this form.)		Head Fernaldalla L. D. 11. O.		Wichita, humani
	Remarks:	(If additional description is r	chlumberger. No casi	ing recovery. f this form.)
II (d) by () () () () () () () () () (li Maina M s			
Signed Stewn K Sarlaw	IVUI	J L D	Signed Silver	WK Karland
1-6-88	1-6	_88	(TE	CHNICIANS
	a_19	356	•	FORM CP-2/3 Rev.01-84

FORM CP-2/3 Rev.01-84