

15-135-01015-00-00

DISTRICT CONSERVATION AGENT'S REPORT

R

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION NW-NW-SE

SEC. 9 TWP. 16 RGE 21W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Elmore

Operator Melch-Alson Mfg. Co. Inc. Address 203 Rule Bldg. Wichita

Field _____ County Miss

Total Depth 4307 Feet.

Plugging Contractor Melch and Alson Mfg. Co. Inc.

Plugging Contractor's License No. _____

Address 203 Rule Bldg. Wichita, Kansas
(Describe Briefly the manner in which the well was plugged)

*Surf Pipe 8 3/4 @ 199 c.w. 175 ft. Cement
Plugged with full mud to 670 feet and
good Plug and 30 ft. Cement Pumped through
Waste Pipe and full mud to 180 feet and 1/2 sec.
hulls and Plug and 15 ft. Cement through Waste
Pipe and full mud to 35 feet and 1/2 sec.
hulls and Plug and 10 ft. Cement to base of
Cedar*

K.M. Brundage
District Conservation Agent

Date Aug. 31 1956

PLUGGING
FILE SEC. 9 T. 16 R. 21W
BOOK PAGE 95 LINE 27

RECEIVED
COMMISSION
09-04-1956
WICHITA, KANSAS