

KCC OIL/GAS REGULATORY OFFICES

Date: 01/11/12

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
  - Complaint
  - Field Report
- RECEIVED**  
JAN 25 2012

Operator License No: 9067  
 Op Name: DayMar Resources  
 Address 1: 234 W 11th Ste A  
 Address 2: P.O. Box 70  
 City: Hays  
 State: Kansas Zip Code: 67601 -3805  
 Operator Phone #: (785) 625-0020

API Well Number: 15-135-25.328-00-00  
 Spot: N/2-NE-SE-NW Sec 12 Twp 20 S Rng 24  E /  W  
 1490 (1516) Feet from  N /  S Line of Section  
 2310 (2306) Feet from  E /  W Line of Section  
 GPS: Lat: 38.33027 Long: 99.92601 Date: 1/11/12  
 Lease Name: Harriet Well #: 1  
 County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

Findings:

8-5/8" @ 776'W/300sxs cement  
 TD @ 4500'  
 5-1/2" @ 4498'W/125sxs cement  
 Port Collar @ 1598' cemented with 125sxs-smd-1/4# flo seal-2%cc--20sxs went to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None Alt.II requirements have been met.

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

JAN 20 2012

KCC DODGE CITY

Form: \_\_\_\_\_

Date: 01/11/12

District: 01

License #: 9067

Op Name: 9067

Spot: N/2-NE-SE-NW Sec 12 Twp 20 S Rng 24  E  W

County: Ness

Lease Name: Harriet Well #: 1

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.328-00-00	1516FNL 2306FWL	N/2-NE-SE-NW	38.33027-99.92601	1	New well, Alt. II completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_