## KCC OIL/GAS REGULATORY OFFICES

Date: <u>01/26/12</u>	District: <u>01</u>	Case #:
	New Situation	Lease Inspection
	Response to Request	Complaint
	Follow-Up	Field Report
Operator License No: 4058	API Well Number: 15-13	5-25,323-00-00
Op Name: American Warrior	Spot: <u>NW-SE-SW-SW</u>	Sec <u>27</u> Twp <u>18</u> S Rng <u>21</u> E / W
Address 1: P.O. Box 399	.335 (377)	Feet from N/ S Line of Section
Address 2: P.O. Box 783188	• •	Feet from E/W Line of Section
City: Garden City	GPS: Lat: <u>38.45205</u>	Long: <u>99.63820</u> Date: <u>1/26/12</u>
State: Kansas Zip Code: 67846 -0399	Lease Name: Mashall	Well #: 2-27
Operator Phone #: (620) 587-3224	County: Ness	
Reason for Investigation:		
Witness Alt.II		
Problem:		
None, cement circulated to surface		
Persons Contacted:		
Findings:		
8-5/8" @227 W/150sxs cement		
TD @ 4229'  5-1/2" @ 4228'W/275sxs cement		
Port Collar @ 1354' cemented with 120sxs-s	md-1/4# flo seal-2%cc-	15sxs went to pit
Total Collar & 1001 Collicities Will 1200/100	1110 17 17 110 0001 27000	rocke work to pit
		1
Action/Recommendations: Follow	w Up Required Yes No	Date:
Alt.II requirements have been met		
The requirements have been more		
**************************************		
Verification Sources:		Photos Taken:
RBDMS KGS	TA Program	
	Courthouse By: Mic	gael Maier
Other:		alas Il Our
RECEIVED		RECEIVED
Send 1 Copy to Conservation Division FEB - 6 2012		- 00/00/000
י בט ט נטונ		FEB 0 8 2012 Form: 02/22/2008
KCC DODGE CITY `		KCC WICHITA

**KCC WICHITA** 

Date: 01/26/12		_	District:	01	<del></del>	License #: <u>4058</u>		
Op Name: <u>4058</u>			Spot: <u>N</u> V	Spot: NW-SE-SW-SW Sec 27 Twp 18 S Rng 21 E W				
County: Ness			Lease.Na	se.Name: Mashall Well #: 2-27				
I.D. Sign Yes	No		Ŋ	Gas Vo	enting	Yes No		
Tank Battery Cond		ole Overflow	ing 🔝	Pit:		ft; Approx. Size:ft. xft.		
Pits, Injection Site Fluid Depth:	_ft; Approx. S	Size:ft	. xft.	<b> </b>	twater Pi ks Visible			
Oil Spill Evidence				Flo	wing Hol	les		
Abandoned Well	Potential Poll	ution Problem	Yes No 🖻	TA	A Wells			
Lease Cleanliness				Мо	nitoring	Records		
Very Good S	atisfactory [	Poor Very	1					
SWD/ER Injection Well	Yes	No	Ness 🖸	Gauge	Connecti	ions Yes No		
Permit #: P						; T/C Annulus:; C/SP Annulus:		
Permit #:P						; T/C Annulus:; C/SP Annulus:		
Permit #: P Permit #: P			thorized: psi thorized: psi			; T/C Annulus:; C/SP Annulus: ; T/C Annulus:; C/SP Annulus:		
· ·	tessure - / tetu	an pai, 1xu	pst	1 40111	<u>ь</u>	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
API Number	Footages	Spot Location	GPS		Well #	Well Status		
15-135-25,323-00-00	377FSL 927FWL	NW-SE-SW-SW	38.45205-99.63	820	2-27	New well, Alt.II completed		