

# KCC OIL/GAS REGULATORY OFFICES

Date: 02/02/12

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-083-21,745-00-00

Op Name: American Warrior

Spot: NE-NW-SW-SE Sec 4 Twp 24 S Rng 21  E /  W

Address 1: P.O. Box 399

1234 Feet from  N /  S Line of Section

Address 2: P.O. Box 783188

2152 Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.98903 Long: 99.63214 Date: 2/2/12

State: Kansas Zip Code: 67846 -0399

Lease Name: Gleason Well #: 1-4

Operator Phone #: (620) 587-3224

County: Hodgeman

**Reason for Investigation:**

Witness Alt.II

**Problem:**

None, cement circulated to surface

**Persons Contacted:**

**Findings:**

8-5/8" @221 W/150sxs cement  
TD @ 4660'  
5-1/2" @ 4652'W/125sxs cement  
Port Collar @ 1435' cemented with 115sxs-smd-1/4# flo seal-2%cc-10sxs went to pit

**Action/Recommendations:**

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met

**Verification Sources:**

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-J Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____		

**RECEIVED**

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

**KCC DODGE CITY**

**RECEIVED**

By: Michael Maier **FEB 13 2012**

**KCC WICHITA**

Form: 02/22/2008

Date: 02/02/12

District: 01

License #: 4058

Op Name: 4058

Spot: NE-NW-SW-SE Sec 4 Twp 24 S Rng 21  E  W

County: Hodgeman

Lease Name: Gleason Well #: 1-4

I.D. Sign  Yes  No

---

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

---

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Oil Spill Evidence

---

Abandoned Well Potential Pollution Problem  Yes  No

---

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

---

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

---

Flowing Holes

---

TA Wells

---

Monitoring Records

SWD/ER Injection Well  Yes  No Hodgeman

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-083-21,745-00-00		NE-NW-SW-SE	38.98903-99.63214	1-4	New well, Alt. II completed