

# KCC OIL/GAS REGULATORY OFFICES

Date: 03/01/12

District: 1

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-135-25341-00-00

Op Name: American Warrior Inc.

Spot: SE NW SE SW Sec 23 Twp 19 S Rng 22  E /  W

Address 1: PO Box 399

918 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

1720 Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.38073 Long: 99.72685 Date: 3/1/12

State: KS Zip Code: 67846 -0399

Lease Name: O'Brate Well #: 5

Operator Phone #: (620) 275-2963

County: Ness

### Reason for Investigation:

Company requested a witness to the Alternate II cementing job

### Problem:

Alternate II cementing requirements have not been met

### Persons Contacted:

Scott Corsair w/ American Warrior

### Findings:

10:29 AM  
TD = 4380  
8.625" Set @ 224 w/ 150sx  
5.5" set 4379' w/ 175 sx  
Company opened port collar @ 1478'.  
Swift Service pumped 125sx SMD 1/4# floseal per sack.  
Circulated 20 sx cement to the pit up the 8.625" X 5.5" annulus.

### Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alternate II cementing requirements have been met.

RECEIVED

MAR 12 2012

KCC WICHITA

### Verification Sources:

Photos Taken: 0

- RBDMS
- T-I Database
- Other: Operator
- KGS
- District Files
- TA Program
- Courthouse

By: Richard W. Lucey

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

RECEIVED

MAR 6 2012

KCC DODGE CITY

Form: \_\_\_\_\_

Date: 03/01/12

District: 1

License #: 4058

Op Name: 4058

Spot: SE NW SE SW Sec 23 Twp 19 S Rng 22  E  W

County: Ness

Lease Name: O'Brate Well #: 5

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status