

15-169-19154-00-00

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. 62-20

LOCATION SE-2E-2W

SEC. 11 TWP. 16 RGE. 3W

SWS

~~Dry Hole~~ _____ Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. D-1 Lease Salina Bldg Co

Operator Lambert, Busboom, Paul Address Salina Kans

Field Assaid County Saline

Total Depth 258 Feet.

Plugging Contractor No pipe recovery, work done by hand.

Plugging Contractor's License No. _____

Address _____

(Describe briefly the manner in which the well was plugged)

*Could only get down to approx. 30ft
due to corrosion and as 5" and 3" were
cemented cut pipe off below flow
depth and put cement cap at top*

PLUGGING
FILE SEC. 11 T. 16 R. 3W
BOOK PAGE 62 LINE 20

3-11-54

Paul Busboom
District Conservation Agent

Date 3-8-54