

15-169-00724-00-00

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION 3 W - 3 W - 3 W

SEC. 11 TWP. 16 RGE. 3W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. 3 Lease Salina Bldg Co.

Lambert & Bushboom Operator Address Salina Kans

Field _____ County Salina

Total Depth 3530 Feet.

(Describe briefly the manner in which the well was plugged)

Grinded pits & circulated,
15 sack cement spotted at 160,
5 sack cement at top of surface
pipe.

FILE 15-169-00724-00-00
BOOK PAGE 116-15

District Conservation Agent

Date 10/11/51 CX

CO. CONSERVATION DIVISION
Wichita, Kansas