

KCC OIL/GAS REGULATORY OFFICES

Date: 02/22/12

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058
 Op Name: American Warrior, Inc.
 Address 1: PO Box 399
 Address 2:
 City: Garden City
 State: KS Zip Code: 67846
 Operator Phone #: (620) 275-2963

API Well Number: 15-083-21746-00-00
 Spot: NW NW NE NW Sec 9 Twp 24 S Rng 21 E / W
 112 (103) Feet from N / S Line of Section
 1430 (1410) Feet from E / W Line of Section
 GPS: Lat: 37.98535 Long: 99.63786 Date: 2/22/12
 Lease Name: Strecker Unit Well #: 1-9
 County: Hodgeman

Reason for Investigation:

Company requested state witness for Alternate II cementing

Problem:

None

Persons Contacted:

None

Findings:

10:00 AM
 Surface casing: 8 5/8" @ 228' w. 150sx cement
 Production casing: 5 1/2' @ 4636' w/ 125sx cement
 Total Depth: 4645'
 Port collar @ 1412' Swift Services pumped 120sx SMD cement, and circulated 20sx to the pit.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

None. Alternate II cementing requirements have been met

RECEIVED
 FEB 27 2012
 KCC WICHITA

Verification Sources:

- | | | |
|---------------------------------------|---|-------------------------------------|
| <input type="checkbox"/> RBDMS | <input type="checkbox"/> KGS | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-1 Database | <input type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input type="checkbox"/> Other: _____ | | |

By: Kenny Sullivan

Photos Taken: 0

Retain 1 Copy District Office
 Send 1 Copy to Conservation Division
 FEB 23 2012

KCC DODGE CITY

Form: _____

Date: 02/22/12

District: 01

License #: 4058

Op Name: 4058

Spot: NW NW NE NW Sec 9 Twp 24 S Rng 21 E W

County: Hodgeman

Lease Name: Strecker Unit Well #: 1-9

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Hodgeman

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status