

KCC OIL/GAS REGULATORY OFFICE

15101216250000

DATE 7/17/92

- New Situation
- Response to Request
- Follow-up

OPERATOR Ritchie Exploration # 4767

NAME 125 N. Market, Suite 1000

LOCATION SW NE NW, SEC 3, T 19 S, R 28 W

& ADDRESS Wichita, KS 67202

LEASE Bosley 3B Well # 1

PHONE NO. \_\_\_\_\_  
OPER. \_\_\_\_\_ OTHER \_\_\_\_\_

COUNTY Lane

REASON FOR INVESTIGATION: Alternate II cement completion

PROBLEM: \_\_\_\_\_

PERSON(S) CONTACTED: Bennie Dills

FINDINGS: Port collar at 2078'. Pumped 350 sx 50/50 Pozmix 6% gel. Cement did circulate.

ACTION/RECOMMENDATIONS: None. Case closed.

photos taken: \_\_\_\_\_

Retain 1 copy Joint District Office  
Send 1 copy Conservation Division

By Dan Goodrow

7/17/92

LEASE INSPECTION

COMPLAINT

FIELD REPORT

RECEIVED  
STATE CORPORATION COMMISSION

JUL 22 1992

CONSERVATION DIVISION  
Wichita, Kansas

LEASE INSPECTION

- YES NONE COMMENTS
- I.D. Sign
  - Tank Battery ; Condition: good  questionable  overflowing
  - Pits, tank battery ; Fluid depth \_\_\_\_\_ft.; approx. size \_\_\_\_\_ft x \_\_\_\_\_ft
  - Pit, injection site ; Fluid depth \_\_\_\_\_ft.; approx. size \_\_\_\_\_ft x \_\_\_\_\_ft
  - Gas venting
  - Oil spill evidence
  - Saltwater evidence ; Surface flow \_\_\_\_\_; seepage\_\_\_\_\_
  - Saltwater pipelines ; Seepage visible Yes/No; tested for leaks Yes/No
  - Flowing holes
  - Abandoned wells
  - TA wells ; Potential poll. prob.\_\_\_\_\_; currently producing\_\_\_\_\_
  - SWD/ER Injection well ; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_psi, Authorized \_\_\_\_\_psi
  - SWD/ER Injection well ; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_psi, Authorized \_\_\_\_\_psi
  - SWD/ER Injection well ; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_psi, Authorized \_\_\_\_\_psi
  - SWD/ER Injection well ; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_psi, Authorized \_\_\_\_\_psi
  - Monitoring records
  - Gauge connections : tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_
  - Gauge connections : tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_
  - Gauge connections : tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_
  - Gauge connections : tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_

Lease cleanliness: very good \_\_\_\_\_ satisfactory \_\_\_\_\_ poor \_\_\_\_\_ very bad \_\_\_\_\_

Water samples taken \_\_\_\_\_

Reports prepared \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

+	+	+	+	+	+	+
+	+	+	+	+	+	+
+	+	+	+	+	+	+
+	+	+	+	+	+	+