

KCC OIL/GAS REGULATORY OFFICES

Date: 03/12/12

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 6569

API Well Number: 15-135-25.360-00-00

Op Name: Carmen Schmitt, Inc.

Spot: S/2-NE-NE-SE Sec 32 Twp 17 S Rng 24  E /  W

Address 1: P.O. Box 47

2270 (2277) Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

330 (308) Feet from  E /  W Line of Section

City: Great Bend

GPS: Lat: 38.52886 Long: 99.99305 Date: 3/12/12

State: Kansas Zip Code: 67530 -0047

Lease Name: Gantz Well #: 2-32

Operator Phone #: (620) 793-5100

County: Ness

Reason for Investigation:

Witness

Problem:

None

Persons Contacted:

Findings:

8-5/8"@224'W/150sxs cement  
TD@4343'  
5-1/2"@4326'W/125sxs cement  
Port Collar @ 1679'W/135sxs-smd-1/4# flo seal-2%cc-15sxs went to pit.

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt.II requirements have been met.

RECEIVED

MAR 23 2012

KCC DODGE CITY

RECEIVED

MAR 28 2012

KCC WICHITA

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier  
Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_

AMJ

Date: 03/12/12

District: 01

License #: 6569

Op Name: 6569

Spot: S/2-NE-NE-SE Sec 32 Twp 17 S Rng 24  E  W

County: Ness

Lease Name: Gantz Well #: 2-32

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.360-00-00	2277FSL 308FEL	S/2-NE-NE-SE	38.52886-99.99305	2-32	Alt.IL requirements have been met.