RCC OIL/GAS REGULATORY OFFICE - IC-MI_ 31(77-00-00

DATE:	8/10/94	() W- 216/7-00 00 [] New Situation			
			[]	Response to	Request Follow-Up
		LOCATION SE SE	SE , SEC 36	, <u>T</u> 18 s,	<u>R</u> 28W
OPERATOR:	Ritchie Exploration,	Inc.	LICENSE #:	4767	
ADDRESS:	125 N Market, Ste. 100	00 ′			Chamland True
ADDRESS:	Wichita, KS 67202		LEASE/WELL	HOMBER.	Shapland Tru
PHONE #:	316-267-4375		COUNTY:	Lane 5-101-21,677	···
LEAS	SE INSPECTION:	COMPLAINT:		D REPORT:	X
		Alternate II cement	ing		
REASON FO	R INVESTIGATION:			<u> </u>	
				Mic - Commis	SSION
PROBLEM:			COMO	1UG 1 5 1994	
		<u></u>	Will Will	CVATION DIVISION	<u></u>
PERSONS CO	ONTACTED: John Neirnl	berger		WANG STOIL	
PINDINGS:	Opened port collar at	2070'. Allied pum	ped in 245 sx ce	ement-65/35 Pc	zmix 8% gel
ኒ# floseal.	Circulated cement to p	pit. Started at 1:	15 p.m. and fini	shed at 1:45	p.m.
					····
· - · · · -			<u> </u>		
	· · · · · · · · · · · · · · · · · · ·				···
		<u>.</u>	-	<u> </u>	
<u>*</u>			•		<u></u> -
	· · · · · · · · · · · · · · · · · · ·				
	· · · · · · · · · · · · · · · · · · ·		PHOTOS TAK	<u> </u>	·
ACTION/REC	COMMENDATIONS: Alte	ernate II cementing	completed.		
			· · · · · · · · · · · · · · · · · · ·		WE
					<u> </u>
· · · · · · · · · · · · · · · · · · ·					
		· · · · · · · · · · · · · · · · · · ·		 	- CAS
·			· · · · · · · · · · · · · · · · · · ·		81
				Steve Midd	lleton
			- BY	8/10/9	