

KCC OIL/GAS REGULATORY OFFICE

15-101-21620-00-00 ALTZ

DATE 7/22/92

New Situation
 Response to Request
 Follow-up

OPERATOR Ritchie Exploration, Inc. #4676

NAME 125 N. Market, Suite 1000

LOCATION E/2 NW SW SW, SEC 25, T 18 S, R 28 W

& ADDRESS Wichita, KS 67202

LEASE E. Shapland Trust B Well # 1

PHONE NO. _____
OPER. _____ OTHER _____

COUNTY Lane API #15-101-21,620

REASON FOR INVESTIGATION: Alternate II cement completion

PROBLEM: _____

LEASE INSPECTION

PERSON(S) CONTACTED: Bennie Dills

FINDINGS: Port collar at 2034', pumped 240 sx 50/50 Pozmix 6% gel. Cement did circulate.

COMPLAINT

ACTION/RECOMMENDATIONS: None.

photos taken: _____

FIELD REPORT

RECEIVED
OIL CORPORATION COMMISSION

JUL 30 1992

Retain 1 copy Joint District Office
Send 1 copy Conservation Division

By Dan Goodfellow
CONSERVATION DIVISION

7/22/92

LEASE INSPECTION

- YES NONE COMMENTS
- I.D. Sign
 - Tank Battery ; Condition: good questionable overflowing
 - Pits, tank battery ; Fluid depth _____ft.; approx. size _____ft x _____ft
 - Pit, injection site ; Fluid depth _____ft.; approx. size _____ft x _____ft
 - Gas venting
 - Oil spill evidence
 - Saltwater evidence ; Surface flow _____; seepage_____
 - Saltwater pipelines ; Seepage visible Yes/No; tested for leaks Yes/No
 - Flowing holes
 - Abandoned wells
 - TA wells ; Potential poll. prob._____; currently producing_____
 - SWD/ER Injection well ; Permit # _____ Pressure-actual _____psi, Authorized _____psi
 - SWD/ER Injection well ; Permit # _____ Pressure-actual _____psi, Authorized _____psi
 - SWD/ER Injection well ; Permit # _____ Pressure-actual _____psi, Authorized _____psi
 - SWD/ER Injection well ; Permit # _____ Pressure-actual _____psi, Authorized _____psi
 - Monitoring records
 - Gauge connections : tubing _____; T/C annulus _____; C/SP annulus _____
 - Gauge connections : tubing _____; T/C annulus _____; C/SP annulus _____
 - Gauge connections : tubing _____; T/C annulus _____; C/SP annulus _____
 - Gauge connections : tubing _____; T/C annulus _____; C/SP annulus _____

Lease cleanliness: very good _____ satisfactory _____ poor _____ very bad _____

Water samples taken _____

Reports prepared _____

+	+	+	+	+	+	+
+	+	+	+	+	+	+
+	+	+	+	+	+	+
+	+	+	+	+	+	+