KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO: Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas

| File No | 29-28 | · | Cou | nty: | Elli | 3 | ···, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | | | | |
|---|--|---------------------------------------|----------|--------------|---------------|-------------|--|--------------|------------------|--------------|-------------------|--|
| Location: | CM ^울 | NW NE | | s | ec. <u>31</u> | Twp | 11 | Rge | 17 | _(E) | _(W) <u>_</u> (W) | |
| Name of Fiel | | | | | | | | | | | | |
| I have this date completed supervision of plugging of: | | | | | | | | | | | | |
| Lease Name:_ | | Hadle | y | ۲, | | | Well | . No | 5 | | | |
| Operator's F | Operator's Full Name: Republic Natural Gas | | | | | | | | | | | |
| Complete Add | ress: | · · · · · · · · · · · · · · · · · · · | Box 126 | Ell | lnwood, | Kans | | | | , | | |
| Plugging Contractor: Barnes & Sons & Globe Cementing Co | | | | | | | | | | | | |
| Address: | | I | Russell, | Kan s | | | Lice | ense No | · | 9 | | |
| Oil Well | ж (| Gas Well | | Input V | Vell | swd | Well_ | - | D & | s A | | |
| Other well as hereafter indicated: | | | | | | | | | | | | |
| Was any delay in plugging operations caused by Conservation Division Agent? Yes No X | | | | | | | | | | | | |
| If yes how long?Reason: | | | | | | | | | | | | |
| | | | | | . | | | | · | | | |
| | | | | | | <u></u> | · · · · · · · · · · · · · · · · · · · | | | | | |
| Operation Completed: Hour 4PM Day 20 Month 4 Year 59 | | | | | | | | | | | | |
| The above well was plugged as follows: | | | | | | | | | | | | |
| 8 5/8" 1081' circulated with cement - $5\frac{1}{2}$ " 3697' with 150 sax cement | | | | | | | | | | | | |
| behind - perforated 3625. | | | | | | | | | | | | |
| Filled with sand to 3610', set 4 sax cement with dump bailer, pulled 2900' | | | | | | | | | | | | |
| $5\frac{1}{2}$ " to 550', circulated hole with heavy mud through $5\frac{1}{2}$ " (Gel), displaced | | | | | | | | | | | | |
| 25 sax cement through 51 at 550, heavy mud to 180, displaced 25 sax | | | | | | | | | | | | |
| cement through $5\frac{1}{2}$ " at 180', heavy much to 35', set bridge and 10 sax | | | | | | | | | | | | |
| cement to | bott | om c ell | lar. | | | | | | | | | |
| Mudding and cementing by Globe Cementing Co. | | | | | | | | | | | | |
| | | | · | | | | | 7 | • | | | |
| Signed: Ledon Teely | | | | | | | | | | | | |
| . (| γ | 12. | _ | _ | | Co | onserva | tion D | ivisi | on Age | int | |
| Reviewed: | 1.10 | ws. | Broc | fé | | | 4 4 · · | • • • • | | ti. | | |
| . // | F | ield Sup | ervisor | | _ | PI I | JGC' | 7.50 | — _{[,} | | 4-59 | |
| Remarks: | | | | | | FILE SEC | <i>3</i> /1 / | R z | 4 | (E)(E) | | |

BOOK PAGE 29 LINE 28