KCC OIL/GAS REGULATORY OFFICES

Date: <u>04/18/12</u>	District: 01	Case #:			
	New Situation	Lease Inspection			
	Response to Request	Complaint			
	Follow-Up	✓ Field Report			
	<u> </u>				
Operator License No: 4058	API Well Number: <u>15-083</u>	3-21765-00-00			
Op Name: American Warrior, Inc.	Spot: <u>SE SW NE NW</u>	Sec 9 Twp 24 S Rng 21 E / W			
Address 1: 3118 Cummings Rd	1100(1087)	Feet from N/ S Line of Section			
Address 2: PO Box 399	1700(1679)	Feet from E/W Line of Section			
City: Garden City	GPS: Lat: <u>37.98267</u>	Long: <u>99.63695</u> Date: <u>4/18/12</u>			
State: KS Zip Code: <u>67846</u> -	Lease Name: <u>Family Farm</u>	Well #: <u>1-9</u>			
Operator Phone #: <u>(620) 275-2963</u>	County: Hodgeman				
Reason for Investigation:					
Company requested state witness for Alte	ernate II cementing	_			
Problem:					
None					
Notice					
Persons Contacted:					
None	RECEIVED				
		APR 2 3 2012			
Findings:		AFR 2 3 2012			
2:00 PM		KCC WICHITA			
Surface casing: 8 5/8" @ 228		1110111111			
Production casing: 5 1/2" @ 4656					
Total Depth: 4662'	SX				
Port collar @ 1400' Swift Services pumpe	ed 200 5⊯ s SMD cement witl	n 20sx circulating to pit			
Action/Recommendations:	follow Up Required Yes No	Date:			
None. All Alternate II cementing requiren	nents have been met				
		RECEIVED			
	•	NEOEIVED			
į		APR ^ '			
Verification Sources:		Photos Tøken; 0			
✓ RBDMS KGS	TA Program	. 0//			
T-I Database District Files	Courthouse By: Kenn	y Sulliyan			
Other:					
Retain 1 Copy District Office		_/			
Send I Copy to Conservation Division		Form			

KCC DODGE CITY

@ W

Date: <u>04/18/12</u>		_	District:	01	Lie	ense #: <u>4058</u>	
Op Name: 4058			Spot: SE	SW NE NW	Sec <u>9</u> Twp <u>24</u>	S Rng <u>21</u> E 🕢 W	
County: Hodgeman Lease N				me: <u>Family Farr</u>	<u> </u>	Well #: <u>1-9</u>	
I.D. Sign Yes	No		A	Gas Venting	Yes √No	নি	
Tank Battery Conc	_	ole Overflow	ing	Pits Fluid Depth:	ft; Approx. Siz	re:ft. xft.	
Pits, Injection Site		Size:ft	. xft.	Saltwater Pi Leaks Visible		Fested for Leaks: Y N	
Oil Spill Evidence				Flowing Hol	les		
Abandoned Well	Potential Polle	ution Problem	Yes No 🔄	TA Wells			
				Monitoring Records			
Lease Cleanliness Very Good	Satisfactory	Poor Ver	y Bad				
SWD/ER Injection We	II Yes	No	Hodgeman 🖸	Gauge Connecti	ions Yes No	쭼	
Permit #: Pressure – Actual: psi; Authorized: ps			thorized: psi	Tubing:; T/C Annulus:; C/SP Annulus:			
Permit #: I			thorized: psi			; C/SP Annulus:	
Permit #: I			thorized: psi	-		; C/SP Annulus: ; C/SP Annulus:	
Permit #: I	Pressure - Actu	ai: psi; Au	thorized: psi	r doing:	; t/C Amulus:	, C/Si Amunus.	
API Number	Footages	Spot Location	GPS	Well #		Well Status	
					_		
	 						
		·	·		·	· · · · · · · · · · · · · · · · · · ·	

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: _____