

INSPECTION REPORT

Case# _____

| | |
|-------------------------------------|---------------------|
| <input type="checkbox"/> | Complaint |
| <input type="checkbox"/> | New Situation |
| <input checked="" type="checkbox"/> | Response to request |
| <input type="checkbox"/> | Follow-up |

Date of Inspection: May 11, 2012

Operator: Rosewood Resources Inc.

License: 33019

Address: 2101 Cedar Springs Rd, Ste. 1500

Location: NE-SW-SE-SE/4 Sec. 10-3-41W

City/St: Dallas Texas 75201

Lease: Zweygardt # 44-10

Phone: (214)-849-9300

County: Cheyenne

Reason for investigation: Response to request.

Problem: No problem identified.

Findings:

- > On the above reported date and inspection was conducted on the Zweygardt # 44-10 gas well.
- > The Zweygardt # 44-10 is located NE-SW-SE-SE/4 of section 10-3-41W. The API # is 15-023-21,074. The Gps location is -101.90222W & 39.80147N. The well was spudded on October 7, 2008 and drilled to a depth of 5,360 feet. The well was plugged back to 1,618 feet and completed as a Niobrara gas well. The well is flowing from the casing and has a 'Big Joe' regulator to control the volume. The well is not equipped with tubing, rods or a pumping unit. The well was producing gas and selling through a meter located NW-SW-NW/4 of section 14-3-41W. The meter could not be read due to the lack of access to a password. Gas could be heard passing through the meter.

Photos: Yes

Action /recommendations:

- > There were no violations noted.

Darrel Dipman PIRT II

(agent)

Darrel Dipman

(signature)

cc: file

May 18, 2012


Rosewood Resources Inc. # 33019

Zweygardt # 44-10

NE-SW-SE-SE/4 Sec. 10-3-41W

Cheyenne County, Kansas

< Lease inspection on May 11, 2012, to check lease for compliance with Kansas Corporation Rules and Regulations regarding the Conservation of Crude Oil & Natural Gas.



Picture shows a view of the Zweygardt # 44-10 active gas well located NE-SW-SE-SE/4 of section 10-3-41W. The Gps location is - 101.90222W & 39.80147N.