

KCC OIL/GAS REGULATORY OFFICES

Date: 04/09/12

District: 01

Case #: _____

New Situation

Lease Inspection

Response to Request

Complaint

Follow-Up

Field Report

Operator License No: 4058

API Well Number: 15-135-25,352-00-00

Op Name: American Warrior

Spot: NW-NW-SE-NW Sec 23 Twp 19 S Rng 21 E / W

Address 1: P.O. Box 399

1420 (1386) Feet from N / S Line of Section

Address 2: P.O. Box 783188

1375 (1397) Feet from E / W Line of Section

City: Garden City

GPS: Lat: 38.38892 Long: 99.72796 Date: 4/9/12

State: Kansas Zip Code: 67846 -0399

Lease Name: Delaney Well #: 2-23

Operator Phone #: (620) 587-3224

County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None, cement circulated to surface

Persons Contacted:

Findings:

8-5/8" @223 W/150sxs cement
TD @ 4371'
5-1/2" @ 4370'W/175sxs cement
Port Collar @ 1450' cemented with 125sxs-smd-1/4# flo seal-2%cc-10sxs went to pit

Action/Recommendations:

Follow Up Required Yes No

Date: _____

Alt.II requirements have been met

Verification Sources:

Photos Taken: _____

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____		

By: Michael Maier

Michael Maier
RECEIVED

Retain 1 Copy District Office
Send 1 Copy to Conservation Division
APR 13 2012

KCC DODGE CITY

APR 16 2012 Form: 02/22/2008

KCC WICHITA

BMX

Date: 04/09/12

District: 01

License #: 4058

Op Name: 4058

Spot: NW-NW-SE-NW Sec 23 Twp 19 S Rng 21 E W

County: Ness

Lease Name: Delaney Well #: 2-23

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25.352-00-00	1386FNL 1397FWL	NW-NW-SE-NW	38.38892-99.72796	2-23	New well, Alt. II completed

Retain 1 Copy District Office
Send 1 Copy to Conservation Division