

KCC OIL/GAS REGULATORY OFFICES

Date: 05/08/12

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-083-21764-00-00

Op Name: American Warrior, Inc

Spot: SW SE NE SW Sec 19 Twp 23 S Rng 22  E /  W

Address 1: 3118 Cummings Road

1529 (1548) Feet from  N /  S Line of Section

Address 2: PO Box 399

2027 (2005) Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.03342 Long: 99.78243 Date: 5/8/12

State: Kansas Zip Code: 67846 -

Lease Name: Craghead Well #: 3-19

Operator Phone #: (620) 275-2963

County: Hodgeman

Reason for Investigation:

Company requested state witness for alternate II cementing job.

Problem:

None

Persons Contacted:

None

Findings:

2:35pm  
 Surface casing: 8.625" @ 222' w/ 150sx cement  
 Production casing: 5.500" @ 4666' w/ 125sx  
 Port collar opened @ 1483', Swift Services pumped 150sx of SMD cement with 20sx circulating to the pit.  
 Port collar closed.

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None. All alternate II cementing requirements have been met.

RECEIVED  
 MAY 15 2012  
 KCC WICHITA

Verification Sources:

Photos Taken: 0

- RBDMS
- T-I Database
- Other: On-site witness
- KGS
- District Files
- TA Program
- Courthouse

By: Kenny Sullivan

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

MAY 11 2012

KCC DODGE CITY

Form: \_\_\_\_\_

*Handwritten initials*

Date: 05/08/12

District: 01

License #: 4058

Op Name: 4058

Spot: SW SE NE SW Sec 19 Twp 23 S Rng 22  E  W

County: Hodgeman

Lease Name: Craghead Well #: 3-19

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Hodgeman

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_