

KCC OIL/GAS REGULATORY OFFICES

Date: 5-10-12

District: 1

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 33793

API Well Number: 15-069-201460001

Op Name: Sunflower Energy LLC

Spot: SWSW Sec 30 Twp 25 S Rng 28  E /  W

Address 1: 10801 Mastin Ste 920

660 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

660 Feet from  E /  W Line of Section

City: Overland Park

GPS: Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Date: \_\_\_\_\_

State: Ks Zip Code: 66210

Lease Name: Irsik Well #: 1 OWW10

Operator Phone #: \_\_\_\_\_

County: Gray

Reason for Investigation:

Alternate II Cementing

Problem:

\_\_\_\_\_

Persons Contacted:

\_\_\_\_\_ Co Rep - Clint Andrews - Crown Cores

Findings:

8 7/8" @ 4-11'; 5 1/2" @ 4980' w/ 150sx. No port collar or DV Tool  
5-9-12 Perforate @ 1000'. Allied pumped 175sx 65/35 Pps 6% gel  
followed by 50sx Class A. Circulate 1/2 bbl good cement to the  
pit.

Not witnessed by KCC

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alternate II Complete

**RECEIVED**  
**MAY 15 2012**

Verification Sources:

- RBDMS
- T-1 Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Ken Schlick  
Kenny Sullivan

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_

*RMV*

Date: \_\_\_\_\_

District: \_\_\_\_\_

License #: \_\_\_\_\_

Op Name: \_\_\_\_\_

Spot: \_\_\_\_\_ Sec \_\_\_\_\_ Twp \_\_\_\_\_ S Rng \_\_\_\_\_  E  W

County: \_\_\_\_\_

Lease Name: \_\_\_\_\_ Well #: \_\_\_\_\_

I.D. Sign  Yes  No

---

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

---

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Oil Spill Evidence

---

Abandoned Well Potential Pollution Problem  Yes  No

---

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

---

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

---

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

---

Flowing Holes

---

TA Wells

---

Monitoring Records

SWD/ER Injection Well  Yes  No

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

| API Number | Footages | Spot Location | GPS | Well # | Well Status |
|------------|----------|---------------|-----|--------|-------------|
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |
|            |          |               |     |        |             |

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_