

KCC OIL/GAS REGULATORY OFFICES

Date: 05/16/12

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 34318
 Op Name: Berexco LLC
 Address 1: 2020 Bramblewood
 Address 2: _____
 City: Wichita
 State: Kansas Zip Code: 67206 -1094
 Operator Phone #: (316) 265-3311

API Well Number: 15-135-24,404-00-01
 Spot: SW-NE-NE-SE Sec 4 Twp 16 S Rng 25 E / W
 2200 (2229) Feet from N / S Line of Section
 350 (345) Feet from E / W Line of Section
 GPS: Lat: 38.68836 Long: 100.08411 Date: 5/15/12
 Lease Name: Randa Well #: 1
 County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

Findings:

TD@4592'
 8-5/8@244"W/
 5-1/2"@4590"W/200sxs
 Port Collar @1977"W/310sxs 60/40-6%gel-1/4#flo--15sxs to pit.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

None Alt.II requirements have been met.

RECEIVED
MAY 29 2012

Verification Sources:

- | | | |
|---|---|-------------------------------------|
| <input checked="" type="checkbox"/> RBDMS | <input type="checkbox"/> KGS | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input type="checkbox"/> Other: _____ | | |

Photos Taken: KCC WICHITA

By: Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

MAY 24 2012

KCC DODGE CITY

Form: 02/22/2008

Handwritten initials

Date: 05/16/12

District: 01

License #: 34318

Op Name: 34318

Spot: SW-NE-NE-SE Sec 4 Twp 16 S Rng 25 E W

County: Ness

Lease Name: Randa Well #: 1

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness

Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines

Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24.404-00-01	2229FSL 345FEL	SW-NE-NE-SE	38.68836-100.08411	1	Alt. II requirements have been met.