EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Range Oil Company, Inc.	License Number: 5120		
Operator Address: 125 N. Market, Suite 1120 Wichita, KS 67202			
Contact Person: John Washburn	Phone Number: (316) 265 - 6231		
Permit Number (API No. if applicable): 15-015-23,901 6060	Lease Name: Seglem		
Source of Waste: Dike Emergency Pit Settling Pit Workover Pit Dilling Pit	Well Number: 3 Source Location (QQQQ): Approx - SE - SE - NW Sec. 16 Twp. 27 R. 6 ✓ East West		
Burn Pit Haul-off Pit Steel Pit Spill / Escape	2190 Feet from North / South Line of Section 2165 Feet from East / West Line of Section Butler County		
Type of waste to be disposed:	Other:		
Amount of waste: 3 No. of loads 180 Barrels	Tons YDS		
Destination of waste: Reserve Pit Haul Off Pit Disposal Well Leas	e Road 🗸 Dike / Berm 🗌 Other:		
If waste is transferred to another reserve pit, is the lease active? Yes No			
Location of waste disposal: Operator Name: Range Oil Company, Inc. Lease Name: Seglem Docket No./API No.: Comments: The majority of fluid was hauled to the Seglem ta was partially filled on 6-10-2011. The pit was en			
The undersigned herby certifies that he / she is			

Called and talked to John Washburn w/ Range Oil Company on November 10, 2011, regarding the CDP-5 that was filed on the Seglem #3, 16-27S-6E, 15-015-23901-0000, Butler Cnty.

Mr. Washburn admitted that fluids were hauled from the reserve pit on the Seglem #3 to the Emergency Pit located on the Seglem lease, P10768, 5240'FSL-3980'FEL. Asked if he had received district permission to dispose of the fluids from the reserve pit in this manner, he stated that no, he had not received district permission. He stated that the fluids hauled into the emergency pit have evaporated.

Jonelle Rains

11/10/2011

DOCKET	P10768	SGA		ADDWORKLTR
LIC	05120	RBAS	WA	ADDWKEXT
OPERATOR	RANGE OIL CO INC	APP RECD:	6/11/2010	SEALEDBY 1
FRAC	NENWNW	APP APPROVED:	7/30/2010	INVESTIGATE
FETS	5240	TACT	, [T	PITEXT
FETE	3980		<u>, </u>	CLOSDATE
SEC	16	PFOR	079	DISTRICT
TWP	27	BBLS	00025	
RGE	6 E	CHLORIDES	035000	COMMENT gps 37.70826 -96.78435
LEASE	SEGLEM	ADAT	073010	
COUNTY	15	ADDINFOLTR	06/08/2010	
	REAURECDAT	REAURDAT	E	REAUTHLTR
DOCKET	001181	SGA		ADDWORKLTR
LIC	00001	RBAS	WA	ADDWKEXT
OPERATOR	DUNNE & STRAIT DRLG CO	APP RECD:		SEALEDBY 2

KCC OIL/GAS REGULATORY OFFICES

Date: 11/14/11	District: 02		(Case #:	
	New Si	tuation	Leas	e Inspection	
	Respon	se to Request	Соп	plaint	
	Follow-	Up	√ Field	l Report	
	<u>—</u>		_		
Operator License No: 5120		mber: <u>15-015-</u> 2			
Op Name: RANGE OIL COMPANY, INC.				27 S Rng 6 V	-
Address 1: 125 N. MARKET				from N/ S Line o	
Address 2: SUITE 1120				from E/W Line o	
City: WICHITA				Date:	
State: KS Zip Code: 67202 -		SEGLEM		Well #: 3	
Operator Phone #: (316) 265-6231	County: But	ller			
Reason for Investigation:					
REQUEST FROM KATHY HAYNES TO	INSPECT EMEI	RGENCY PIT	@ TANK B	ATTERY.	
Problem:					
FLUIDS REMOVED FROM SEGLEM # 3 BATTERY.	DRILL PITS W	ERE HAULEI	O TO EMER	GENCY PIT @ TA	NK
Persons Contacted:					
NONE					
Findings:					
1. LOCATED SEGLEM # 3 @ -096.78156 37. AND IS IN OPERATION. DRILL PITS HAVE E THERE WAS STANDING FLUIDS IN A 25' CI DEEP). RAN FIELD CHLORIDE TEST, FLUID 2. LOCATED TANK BATTERY EMERGENCY EMERGENCY PIT MEASURED 16' X 20' X 5' RAN FIELD TEST ON FLUIDS FROM BOTTO CENTER OF PIT, DRILLED 12"-18" DEEP, R PIT. NEITHER FLUIDS OR PIT CLAY LINER HAULED INTO THIS EMERGENCY PIT.	BEEN CLOSED AI RCLE AROUND V PS WERE NOT RE PIT @ -096.7843 , W/APPROXIMA DM OF PIT, NOT F ETRIEVED CLAY	ND AREA HAS WELL HEAD AN ECORDABLE, S 18, 37.70830, N TELY 5 BBLS F RECORDABLE SOIL& FLUIDS	BEEN LEVEI ND PUMPING SHOWED BE W NW NE NV FLUID IN BOT , (RAIN WATI S, NO SIGN C	LED BACK TO GRAD BUNIT. (5-10 BBLS), ING RAIN WATER. V 5,260' FSL 3.933' F TOM OF PIT (8"-10" ER). RAN AUGER IN' DF ANY ROTARY MU	EL. DEEP. TO
Action/Recommendations:	Follow Up Required	Yes No	□ Da	te:	·····
CC JEFF K., KATHY H., JONELLE R.					
Verification Sources:				Photos Taken: Y	ES
RBDMS KGS T-I Database District Files Other: LEASE INSPECTION Retain 1 Copy District Office	TA Program Courthouse	By: DUAN	E KRUEGER	Kuy	

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: 11/30/2011

Date: <u>11/14/11</u>	District: 02		Lice	nse #: <u>5120</u>	
Op Name: <u>5120</u>	Spot: SE SE	NWSe	c <u>16</u> Twp <u>27</u>	S Rng 6	_VE √W
County: Butler	_ Lease Name: S	SEGLEM		Well #: 3	
I.D. Sign Yes No	☐ Ga	s Venting Yes	No		•
Tank Battery Condition Condition: Good Questionable Overflowing		Pits aid Depth:	ft; Approx. Size	e:ft.	xft.
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. x		Saltwater Pipeline Leaks Visible:		ested for Leak	5: Y N
Oil Spill Evidence		Flowing Holes			
Abandoned Well Potential Pollution Problem	Yes No 🗇	TA Wells			
Lease Cleanliness		Monitoring Reco	rds		
Very Good ✓ Satisfactory Poor Very B	1 1				
SWD/ER Injection Well Yes No Permit #: Pressure - Actual: psi; Author		auge Connections		· C/SP A	nnulus:
Permit #: Pressure - Actual:psi; Author		ubing:			
		ubing:			
	orized: psi Tu	ubing:	T/C Annulus:	; C/SP A	onulus:
API Footages Spot Location	GPS	Well Number		Well Status	
					
					
					· · ·-
			<u></u>		
·			<u> </u>		<u></u>



RANGE OIL CO., SEGLEM TANK BATTERY, NW NW NE NW 16-27-6E BU.

PICTURE SHOWS: FRONT OF TANK BATTERY

- 1. LEASE ID SIGN IN PLACE
- 2. AREA HAS BEEN ROCKED FOR EROSION CONTROL
- 3. NO SIGNS OF ANY FLUIDS BEING SPILLED



RANGE OIL COMPANY, SEGLEM TANK BATTERY NW NW NE NW 16-27-6E BU.

PICTURE SHOWS: BACKSIDE OF TANK BATTERY1.

- SMALL SHORT PIECES OF PIPE LAYING AROUND.
 - 2. NO SIGN OF ANY SPILLAGE.



RANGE OIL COMPANY, SEGLEM TANK BATTERY, NW NW NE NW 16-27-6E BU.

PICTURE SHOWS: PIT AREA @ NORTH END OF TANKBATTERY

- 1. 16' X 20' X 5'
- 2. 5 BBLS FLUID (8"-10" DEEP)
- 3. RAN CHLORIDE FIELD TEST (NOT RECORDABLE)
- RAN AUGER IN BASE OF PIT, 12"-18" RETRIEVED CLAY AND FLUIDS, NO SIGN OF ANY ROTARY MUD.



RANGE OIL COMPANY, SEGLEM # 3 SE SE NW 16-27-6E BU.

PICTURE SHOWS: SEGLEM # 3 WELL SITE

- 1. WELL IN OPERATION
- 2. 25' CIRCLE OF FLUIDS STANDING @ WELL SITE. (RAIN WATER)
- 3. PITS HAVE BEEN CLOSED AND AREA LEVELED BACK TO GRADE

Duane Krueger

From: Sera; To: Bubject; Attachments:

Jeff Nock
Thursday, November 10, 2011 3 48 PM
Duane Knugger
PW WASTE TRANSFER INTO EMERGENCY PIT SEGLEM SEC 16-278-06E BUTLER CTY
SSSC-41111010030 pdf

Duane,

Read Kathy's email below and conduct an inspection of the Seglem tank battery site. A field report and a sost sample are being requested by EPR department. Let me know if you have any questions

JeĦ

From: Kathy Haynes Sank: Thursday, November 10, 2011 3:03 PM To: Jeff Klock CC: Jonede Rams Bubject: WASTE TRANSFER INTO EMERGENCY PIT SEGLEM SEC 16-275-06E BUTLER CTY

We received this CDP-5 for the Seglem drall pit that had been inspected with requirements of fluid removal after 96 hrs. The CDP-5 indicated they took fluids to their emergency pit. for the Seglem tank battery [see attached emergency pit anp info]. Talked to Jonelle who called operator and they did indeed remove the fluids from drill pit to the emergency pit. When someone is in the area could they please take a poil sample from center of emergency pit and photo and send a report into us. Jonelle has talked to legal and they are going to pursue this, if you have any questions give me a call. Thanks

Ps. the pit they mention is closed is the drift pit - not the emergency pit