

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____
LOCATION SE-SE-NE
SEC. 9 TWP 11 RGE. 18W

Dry Hole _____ Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Meistrell

Operator Shade & Berry Address 401 Ritz Bldg. Tulsa, Okla.

Field _____ County Ellis

Total Depth 3563' Feet.

Plugging Contractor Transit Corporation.

Plugging Contractor's License No. _____

Address 1516 Liberty Bk. Bldg. Oklahoma City, Okla.
(Describe briefly the manner in which the well was plugged)

Surface pipe - 8 5/8" @ 1196' c.w.c. 650 sx.

Mud to 275' from top, 1/2 sx. hulls, H.O.W.C.O. plug and 15 sx. cem.

through drill-pipe. Mud to 40' from top, 1/2 sx. hulls, H.O.W.C.O. plug

and 10 sx. cem. to base of cellar.

Wilton Gulford
District Conservation Agent

Date 7-11-56

RECEIVED
STATE CORPORATION COMMISSION

JUL 12 1956

PLUGGING
FILE SEC 9 T11 R 18w
BOOK PAGE 80 LINE 1

CONSERVATION DIVISION
Wichita, Kansas